



Section A - Accident Details

Registration Number	SHB178R
Case Reference Number	TAX/11/22/2051
Registration Date	30/11/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	SIM KAY FOO
Type of Accident	Head to Rear
Accident Date and Time	25/11/2022 10:40 PM
Accident Reported Date and Time	26/11/2022 8:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116963
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	27/11/2022 8:55 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$500.00
Total Spray Cost	\$888.00	\$370.00
Total Spare Part Cost	\$2,926.78	\$1,366.18
Total Other Cost	\$1,000.00	\$340.00
TOTAL COST	\$6,014.78	\$2,576.18 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang(LKK) / NTUC
ARC / Surveyor Sign Off Date	29/11/2022 2:26 PM	29/11/2022 12:08 PM
Signature		
Remarks	PART BY PART / BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :quoqiang@lkkauto.com HP:82880282	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0384	Invoice Number	
Quotation Date	30.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,200.00	\$500.00
Total Labour	\$1,200.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$230.00	\$0.00
TO RESPRAY REAR PANEL	\$230.00	\$150.00
Total Spray Painting & Panel Beating	\$888.00	\$370.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,000.00	\$340.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Replace
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	Replace
		10359003	FINISHER-RR BPR - RH	0.00	\$47.42	0.00	\$0.00	Replace	Not Given
		10359002	FINISHER-RR BPR - LH	0.00	\$47.42	0.00	\$0.00	Replace	Not Given
		10465727	BRACKET ASM-RR BPR FASCIA SI-RH	0.00	\$29.85	0.00	\$0.00	Replace	Not Given
		10465723	BRACKET ASM-RR BPR FASCIA SI - LH	0.00	\$29.84	0.00	\$0.00	Replace	Not Given
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$46.08	0.00	\$0.00	Replace	Not Given
		10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$13.20	0.00	\$0.00	Replace	Not Given
		10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$12.90	0.00	\$0.00	Replace	Not Given
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$12.90	0.00	\$0.00	Replace	Not Given
		10449056	BRACKET-RR BPR FASCIA LWR MTG - RH	0.00	\$12.80	0.00	\$0.00	Replace	Not Given

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2022

User ID : PohSuan

		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$12.80	0.00	\$0.00	Replace	Not Given	X
		10327894	BAR ASM-RR BPR IMP	0.00	\$339.76	0.00	\$0.00	Replace	Check	X
		10726677	LAMP ASM-RR FOG - RH	0.00	\$189.07	0.00	\$0.00	Replace	Not Given	X
		10726676	LAMP ASM-RR FOG - LH	0.00	\$36.30	0.00	\$0.00	Replace	Not Given	X
		10376550- WSD	SENSOR-RR PARK DIST CONT	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		10395721- SEPP	PANEL ASM-RR END	1.00	\$708.66	100.00	\$0.00	Replace	Repair	R
Total					\$2,593.16		\$890.24			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		10327894	BAR ASM-RR BPR IMP	1.00	\$339.76	10.00	\$305.78	Replace	Replace
		10726677	LAMP ASM-RR FOG - RH	1.00	\$189.07	10.00	\$170.16	Replace	Replace
Total					528.83		475.94		

1,366.18
+ 500.00
+ 710.00

2,576.18