



Your Ref : CDMCG21000753

Date: 18th Jan 2023

Our Ref : CS/EGI23000224/Pwy3e2

M/s Ergo Insurance Pte Ltd
8 Temasek Boulevard, #04-01
Suntec Tower Three
Singapore 038988
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YP 6143B
ACCIDENT ON 20/04/2021**

Instruction was received to inspect the vehicle Reg. No. YP 6143B. The inspection was conducted on 09/01/2022 at the premises of M/s 517 Airport Road, Singapore 539942.

The following vehicle information was recorded:

Registration Number	: YP 6143B
Make/Model	: Mitsubishi Canter FEB21ER4SDEB (CBU)
Year of Registration	: 2017
Body Colour	: White
Chassis Number	: FEB21EA21265
Engine Capacity	: 2998 cc

The vehicle sustained damages at the front portion and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 85,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 26,902.00)
Nett Liability	<u>S\$ 58,098.00</u> =====

Vehicle Inspected By:



SHERWIN BEH SWEE YANG

Technical Investigator



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.