

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER	1	\$ 500	2,432.00	R
2	FRONT BUMPER FIXING PARTS	1	\$	195.00	X
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	86.00	X
4	FRONT BUMPER GRILLE - CENTER	1	\$	179.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	571.00	X
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	635.00	X
7	FRONT BUMPER TRIM COVER - LH / RH	2	\$	364.00	X
8	FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$	84.00	X
9	RADIATOR GRILLE	1	\$	1,578.00	CR
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$	210.00	?
11	AIR CONDITIONER STICKER	1	\$	9.00	NEC
12	CAUTION SIGN STICKER	1	\$	16.00	NEC
13	FRONT BUMPER FOAM FILLER PIECE	1	\$	211.00	?
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$	847.00	?
15	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$	136.00	?
16	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	?
17	FRONT BUMPER AIR GUIDE - LH / RH	2	\$	56.00	?
18	FRONT BUMPER AIR GUIDE SEAL - RH OUTER	1	\$	9.00	?
19	FRONT BUMPER AIR GUIDE - UPPER CENTRE	1	\$	14.00	?
20	FRONT BUMPER CATCH HOOK	1	\$	71.00	X
			\$ 7,725.00		

SUB TOTAL SPARE PARTS - FRONT


ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 9601 X - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	4 UN
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500
3	TO RESPRAY FRONT BUMPER.	\$ 900.00	550
TOTAL LABOUR CHARGES - FRONT		: \$ 2,310.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: MODA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT NO PLATE	S/N	\$ 80.00	cr ~
TOTAL SPARE PARTS - FRONT		:	\$ 7,805.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - REAR

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
1	REAR BUMPER	1	\$	2,317.00	(✓)
2	REAR BUMPER FIXING PARTS	1	\$	201.00	X NN
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	36.00	✓
4	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$	67.00	✓
5	REAR BUMPER SPOILER	1	\$	264.00	✓
6	REAR WHEEL HOUSING ADAPTER - LH / RH	2	\$	84.00	X
7	REAR BUMPER REFLECTOR - LH / RH	2	\$	92.00	X
8	REAR INNER TAIL LIGHT - LH / RH	2	\$	1,948.00	X
9	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$	68.00	X
10	REAR BUMPER REINFORCEMENT BEAM	1	\$	642.00	✓
11	REAR BUMPER BRACKET - LH / RH	2	\$	63.00	✓
12	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	531.00	X
13	REAR PARKING AID SEAL RING	4	\$	10.00	X
14	REAR BUMPER WIRING SET	1	\$	572.00	X
15	REAR LID	1	\$	3,657.00	deny
16	REAR LID FLAP GASKET	1	\$	229.00	✓
17	REAR LID LOCK	1	\$	211.00	X
18	REAR LID LOCK COVER	1	\$	8.00	X
19	REAR LID LOCK STRIKER	1	\$	56.00	X
20	PACKING ADHESIVE	1	\$	21.00	NN
			:	\$	11,077.00

SUB TOTAL SPARE PARTS - REAR

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	AUDI EMBLEM	1	\$ 144.00	N/L
22	"A3" INSCRIPTION	1	\$ 104.00	N/L
23	LIFT CYLINDER - LH / RH	2	\$ 312.00	X N/L
24	LIFT CYLINDER HOSE	1	\$ 78.00	X N/L
25	REAR NO PLATE	S/N	\$ 60.00	not Dnt
26	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS - FRONT & REAR		:	\$ 20,080.00	
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 8,562.00	
GRAND TOTAL		:	\$ 28,642.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 9601 X - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ Nett 280.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ Nett 280.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00 1000	
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$ 3,000.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ Nett 192.00	
TOTAL LABOUR CHARGES - FRONT & REAR		: \$ 8,562.00	

8 days

P/P

4/1/22
12 pm

1rfm  90097659
IRFAN