

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1173/2022/EQ
DATE : 30-Dec-22
WIP : 56886

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian/Irfan

8 days exclude 1 Sunday

Johnny Boo 23 Mar 23

OWNER'S NAME : MR TAY JOO KIAT (ZHENG YUJI)
ADDRESS : 78 CHOA CHU KANG AVENUE 5
#04-33
SINGAPORE 688200
TELEPHONE : HP +65 96819832
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800142539-04
VEHICLE NO : **SMF 9601 X**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 29/11/2018
ENGINE NO : CZE 846164
CHASSIS NO : WAUZZZ8V0K1002911
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Dec-22
PLACE OF ACCIDENT : ALONG AYE TOWARDS ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 9601 X - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
3	TO RESPRAY FRONT BUMPER.	\$	900.00	\$ 550.00
TOTAL LABOUR CHARGES - FRONT		: \$	2,310.00	\$ 1,050.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 9601 X - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	<i>c/f</i> S/N	\$ 280.00	\$ 1,050.00 \$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N	\$ 280.00	\$ 280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	\$ 1,000.00
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	3,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 8,562.00	\$ 3,902.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,432.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00	
7	FRONT BUMPER TRIM COVER - LH / RH	2	\$ 364.00	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 84.00	
9	RADIATOR GRILLE	1	\$ 1,578.00	\$ 1,262.40
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	
11	AIR CONDITIONER STICKER	1	\$ 9.00	\$ 6.64
12	CAUTION SIGN STICKER	1	\$ 16.00	\$ 12.40
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
15	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	
16	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
17	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 56.00	
18	FRONT BUMPER AIR GUIDE SEAL - RH OUTER	1	\$ 9.00	
19	FRONT BUMPER AIR GUIDE - UPPER CENTRE	1	\$ 14.00	
20	FRONT BUMPER CATCH HOOK	1	\$ 71.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 7,725.00	\$ 1,281.44

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - FRONT

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>1,281.44</i>
21	FRONT NO PLATE	S/N	\$ 80.00	\$	<i>60.00</i>
TOTAL SPARE PARTS - FRONT		:	\$ 7,805.00	\$	<i>1,341.44</i>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 1,341.44
1	REAR BUMPER	1	\$ 2,317.00	\$ 1,853.60
2	REAR BUMPER FIXING PARTS	1	\$ 201.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	
4	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 67.00	
5	REAR BUMPER SPOILER	1	\$ 264.00	
6	REAR WHEEL HOUSING ADAPTER - LH / RH	2	\$ 84.00	
7	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
8	REAR INNER TAIL LIGHT - LH / RH	2	\$ 1,948.00	
9	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$ 68.00	
10	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00	
11	REAR BUMPER BRACKET - LH / RH	2	\$ 63.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
13	REAR PARKING AID SEAL RING	4	\$ 10.00	
14	REAR BUMPER WIRING SET	1	\$ 572.00	
15	REAR LID	1	\$ 3,657.00	\$ 2,925.60
16	REAR LID FLAP GASKET	1	\$ 229.00	
17	REAR LID LOCK	1	\$ 211.00	
18	REAR LID LOCK COVER	1	\$ 8.00	
19	REAR LID LOCK STRIKER	1	\$ 56.00	
20	PACKING ADHESIVE	1	\$ 21.00	\$ 16.80
SUB TOTAL SPARE PARTS - REAR		:	\$ 11,077.00	\$ 6,137.44

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9601 X - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	6,137.44
21	AUDI EMBLEM	1	\$	144.00	\$ 114.80
22	"A3" INSCRIPTION	1	\$	104.00	\$ 82.80
23	LIFT CYLINDER - LH / RH	2	\$	312.00	
24	LIFT CYLINDER HOSE	1	\$	78.00	
25	REAR NO PLATE	S/N	\$	60.00	\$ 60.00
26	SUNDRIES		\$	500.00	\$ 2.56
TOTAL SPARE PARTS - FRONT & REAR			:	\$ 20,080.00	\$ 6,397.60
TOTAL LABOUR CHARGES - FRONT & REAR			:	\$ 8,562.00	\$ 3,902.00
GRAND TOTAL			:	\$ 28,642.00	\$ 10,299.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/03/23



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT