

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1065X

Make : HYUNDAI

Model : IONIQ

Date: 12/27/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Scr \$459.40
10	REAR BUMPER CLIPS			IVC \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			Scr \$451.25
1	REAR BUMPER REINFORCEMENT			XWIV \$394.80
1	REAR BUMPER TOWING COVER			Scr \$98.80
1	REAR BUMPER REINFORCEMENT BRACKET LH			XWV \$138.10
	SUB TOTAL		1031.45	\$1,564.35
	LESS 20%		206.29	\$312.87
	DISCOUNTED TOTAL		825.16	\$1,251.48
	REAR NUMBER RUBBER MAT			IVC \$50.00
	REAR BUMPER REVERSE SENSOR			-10% Short \$180.00
		NETT	212	\$230.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	REMOVE/REFIX REVERSE SENSOR			50 \$80.00
	TOTAL LABOUR		650	\$780.00
	ESTIMATE TOTAL		1687.16	\$2,261.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after

+15 =

total L/S = 20% = 337.43
 = 1349.73
 ≈ 1350 #
 3 days.

27/12/22

3pm 3 days

1rfm L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: