

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/C7/23000238/4pg3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S2G 505Kat Workshop m/s Spent work

of _____

Insured: GBE 248X

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 50k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 274 30482

Vehicle: IN / OUT

Veh No: S2G 505K Yr Regn: 03/10/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA / GLSMake: Hyundai Elantra c.c. 1591Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 150424 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHD841CMH14199536Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. _____ mm

L/Bal. 6 mmD.O.A. 09/01/23 D.O.I. 9/1/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orSee Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27/11/16CV 22-1-22
hardly 1758.4028/1/23 1/5 & 12.700 inbound Ken.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

SPEEDWERKZ PRIVATE LIMITED
1 KAKI BUKIT AVENUE 6, #01-73, AUTOBAY, SINGAPORE 417883
Tel: 96195936 / info@speedwerkz.biz

Not Available
9/1/23
1/5 @ 12,700/
Sday J.

VEHICLE NUMBER: SLG5061L
MAKE & MODEL: HYUNDAI ELANGTRA
DOA: 9/1/22
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT HEAD LAMP @1635	2	\$3,270.00	1/2 C
FRONT HEAD LAMP LOWER BRACKET @33.60	2	\$67.20	X
FRONT SUPPORT PANEL	1	\$1,202.20	X
FRONT BUMPER	1	\$966.20	— 581.40
FRONT BUMPER SIDE RETAINER @38.4	2	\$76.80	—
FRONT BUMPER REINFORCEMENT	1	\$627.00	— 435
FRONT BUMPER LOWER SPOILER	1	\$352.10	X
FRONT BUMPER INNER SPONGE	1	\$186.20	— 130.20
FRONT BUMPER CENTRE BLACK MOULDING @41.70	2	\$83.40	X
FRONT BUMPER FOG LAMP COVER @58.70	2	\$117.40	X
FRONT FENDER @1272.00	2	\$2,544.00	X
FRONT FENDER DUST COVER @112.30	2	\$224.60	X
FRONT GRILLE	1	\$420.00	—
FRONT LUGE @58.60	2	\$117.20	X
FRONT BONNET	1	\$1,452.00	—
REAR BOOT LID TOP GARNISH	1	\$987.50	X
REAR BOOT LID TOP GARNISH BLACK COVER inner	1	\$86.50	—
REAR LOGO	1	\$41.70	X
REAR BOOT LID	1	\$1,960.20	—
REAR BOOT LID LOGO	1	\$215.60	— 60
REAR BOOT LID ELANTRA EMBLEM	1	\$38.40	—
REAR BOOT LID REFLECTOR @484.50	2	\$969.00	— 851.80
REAR BOOT LID INNER LOCK	1	\$175.00	—
REAR BOOT LID RUBBER	1	\$232.00	— 198.60
REAR BUMPER	1	\$865.00	— 581.20
REAR BUMPER DIFFUSER	1	\$424.80	— 231.00
REAR BUMPER REFLECTOR @289.00	2	\$578.00	— 50
REAR BUMPER SIDE RETAINER @30.00	2	\$60.00	—
REAR BUMPER REINFORCEMENT	1	\$417.20	— 378.10
REAR BUMPER CENTRE PLASTIC BRACKET	1	\$90.00	—
REAR BUMPER REINFORCEMENT BRACKET @93.60	2	\$187.20	—
REAR BUMPER REVERSING SENSOR @245	1	\$980.00	2005/N S/N
REAR BOOT LOCK ANTENNA	1	\$206.00	—
REAR BUMPER PLATE LAMP @61.20	2	\$122.40	X
REAR END PANEL	1	\$544.80	—
REAR END PANEL TOP GARNISH	1	\$75.00	—
REAR FENDER INNER TRIM @346.00	2	\$692.00	— 562
REAR FENDER UNDER SHIELD @78.20	2	\$156.40	—
REAR SPARE TYRE PANEL	1	\$978.00	—
REAR SPARE TYRE PANEL TOP COVER	1	\$216.00	—
TAILLAMP @802.20	2	\$1,604.40	— 1196
TAILLAMP PANEL @212.30	2	\$424.60	— 126
REAR EXHAUST SILENCER BOX	1	\$793.00	X
REAR EXHAUST SILENCER BOX INSULATION PANEL	1	\$97.20	X
REAR WINDSCREEN GLASS MOULDING	1	\$98.30	X
REAR SENSOR HARDNESS WIRE	1	\$347.00	— 245.00

\$26,369.50
Less 20 % \$5,273.90
Sub Total \$21,095.60

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT & REAR NUMBER PLATE <i>scr / buff</i>	1 Set	\$90.00	<i>80</i>
REAR BUMPER CLIP <i>res</i>	1 Set	\$60.00	<i>40</i>
REAR FENDER INNER TRIM CLIP <i>res</i>	2 Set	\$90.00	<i>50</i>
REAR GLASS SEALANT <i>17</i>	1	\$100.00	<i>X</i>
REVERSING CAMERA <i>shut</i>	1	\$650.00	<i>300</i>

Sub Total \$990.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$280.00	<i>30</i>
APPLY ANTI RUST CHEMICAL		\$200.00	<i>120</i>
REMOVE AND REFIX REAR GARNISH TRIMMING ETC		\$180.00	<i>80</i>
REMOVE AND REFIX RENEW REVERSING SENSOR		\$150.00	<i>70</i>
REMOVE AND REFIX EXHUAUST PIPE		\$150.00	<i>11X</i>
REMOVE AND REFIX REAR WINDSCREEN		\$150.00	<i>11X</i>
KNOCK DENTS ON REAR DAMAGE PORTION , CUT , WELDING , AND RENEW PARTS		\$2,500.00	<i>1800</i>
TO SPRAY PAINTING AND ETC		\$2,200.00	<i>1800</i>

Sub Total \$5,810.00

Grand Total \$27,895.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P#141698
202
P-1133592
S.N-670
L-3880