

(08/11/13) wef

ASS. REC. BT: Marcus

REF:

CCG/A1623000246/U93

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM2 21347

at Workshop m/s H.

of \_\_\_\_\_

Insured: SMH 11192

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$99k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.3 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LIA 40610

Veh No: SM2 21347 Yr Regn: 16/04/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / CN7

Make: Hyundai Avante c.c. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 103979 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH LN 41 E.TNU 172610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 07/01/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.I. 9/1/23

Date / Time Action / Instruction 02/12/21

16/1/23 TP owner want PIP repair  
PIP \$200.56 in front Alex

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS, SI

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

VEHICLE No: SMZ 2134T

Not Authorized  
9/1/23  
P/P \$5200.56  
3 days.

1PC	BOOTLID	as/gerf	2023.20	\$2,782.00
1PC	BOOTLID REAR LOGO	11		\$75.80 X
1PC	BOOTLID 'AVANTE' EMBLEM	11		\$42.00
1PC	BOOTLID 'S' EMBLEM	su		\$35.00 X
1PC	BOOTLID REFLECTOR CENTRE	one		\$962.20
1PC	BOOTLID INNER LOCK	Daye		\$148.00
1PC	BOOTLID WEATHERSTRIP	11		\$166.00 X
1PC	REAR BUMPER	as/12	470.60	\$481.00
1PC	REAR BUMPER CENTRE GARNISH	grand	340.60	\$354.00
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11		\$130.00 X
1PC	REAR BUMPER SPONGE	NF		\$245.00 X
1PC	REAR BUMPER REINFORCEMENT	as	294.60	\$329.00
2PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$151.00	11		\$302.00 X
2PCS	REAR BUMPER REINFORCEMENT TOP BRACKETS @\$25.00	11		\$50.00 X
3PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$25.00	7w1		\$75.00
1SET	REAR BUMPER CLIPS	11		\$50.00
1PC	REAR END PANEL	11		\$537.00 X
1PC	REAR END PANEL TOP GARNISH	7w1	106.60	\$188.90
2PCS	TAILLAMPS @\$659.00	11		\$1,318.00 X
				\$8,270.90
			LESS20%	\$6,616.72

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	shut	\$280.00	200
1PC	REAR END PANEL SEALANT	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$100.00	60
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO SPRAY RUST PROOFING	\$100.00	30
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	550
TO PUTTY & SPRAY PAINTING	\$1,500.00	600
TOTAL	\$9,996.72	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

1-4573.2  
202  
3610.56  
200  
1390  
5200.56