



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date	: 17/05/2023	Reg No	: YP6192J
To	: ERGO INSURANCE PTE. LTD.	Model	: ISUZU / FRR90SUQA-C
Attn.	:	Chassis No	: JALFRR907H7000027
Office / Mobile	:	Engine No	: 4HK1575312
Email Address	:	Quotation No.	: 181615
		Ref. No.	: GBE/SVC/SALES-HQ/325-1912
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/12/2022
Attn.	: CATHERINECHONGKL	Policy No.	: 5114070704-02
Office / Mobile	:	Claim Type	: TP CLAIM - ERGO INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

SPECIAL NETT ITEMS

1	ALUMINIUM PLATE 4' X 10' <i>bt</i>	3	<i>2580</i>	<i>1450</i> 1650.00
2	SQUARE TUBE METAL 3" X 1 1/2" <i>bt</i>	1		<i>170</i> 270.00
3	PLYWOOD <i>cm</i>	1		<i>160</i> 260.00
4	METAL PLATE <i>repair</i>	1		<i>R</i> 380.00
5	ANGLE BAR <i>bt</i>	1		<i>100</i> 150.00
6	SPRING LOCK <i>nw</i>	1		<i>120</i> 160.00
7	RUBBER <i>new</i>	1		<i>60</i> 90.00
8	SILICONE <i>n</i>	4		160.00
9	RIVET <i>n</i>	100		60.00
10	COMPANY LOGO <i>n</i>	1		<i>300</i> 400.00

PARTS TOTAL:

3580.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	<i>1900</i>	<i>1200</i> 1500.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC		<i>700</i> 900.00

LABOUR TOTAL :

2,400.00

SUB-TOTAL :

5,980.00

GST @ 8% for \$ 5,980.00

478.40

GRAND TOTAL (S\$) :

6,458.40

2580
1900
4480
208

3584
45-3,550 / 4 days

FUSO AIRMAN.

biSAFE
ST & R





GOLDBELL
ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 2 / 2

ESTIMATE

Date	: 17/05/2023	Reg No	: YP6192J
To	: ERGO INSURANCE PTE. LTD.	Model	: ISUZU / FRR90SUQA-C
Attn.	:	Chassis No	: JALFRR907H7000027
Office / Mobile	:	Engine No	: 4HK1575312
Email Address	:	Quotation No.	: 181615
		Ref. No.	: GBE/SVC/SALES-HQ/325-1912
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/12/2022
Attn.	: CATHERINECHONGKL	Policy No.	: 5114070704-02
Office / Mobile	:	Claim Type	: TP CLAIM - ERGO INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : CATHERINECHONGKL

DATE / TIME : 18/05/23 P 1450

SURVEYOR : RASUL

MOBILE NO : 96010068

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 4 days

REMARKS : Rep after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FUSO **AIRMAN.**

biSAFE
S T A R

