

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG23000252/TNP3E2**Date:** 04/05/2023**REFERENCE**

|                   |               |                  |            |                        |
|-------------------|---------------|------------------|------------|------------------------|
| Insured/Claimant: | LEOW KWEE HAR | Policy No:       | 7220144895 |                        |
| Date of Loss:     | 04/01/2023    | Nature of Claim: | OD         | Claim No: 2128953706SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                            |             |                   |
|-----------------------------|--------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLB6322D</b>                            |             |                   |
| Make & Model:               | AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A) | Engine No:  | DFY321661         |
| Reg. Date:                  | 15/12/2022 (Man. Year: 2022)               | Chassis No: | WAUZZZGY4NA049066 |
| Colour:                     | Blue                                       | Odometer:   | 924 km            |
| Engine Capacity:            | 1498 cc                                    |             |                   |
| Market Value/New Car Price: | S\$168,000.00                              |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>          |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/45 R17       | Rear Tyre Size:  | 225/45 R17       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 10,449.00         | 136.40            | 10,312.60         | 98.69         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 5,122.00          | 2,272.00          | 2,850.00          | 55.64         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>15,571.00</b>  | <b>2,408.40</b>   | <b>13,162.60</b>  | <b>84.53</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b> | 1,245.68          | 192.67            | 1,053.01          | 84.53         |
| <b>Nett Amount (S\$)</b>      | <b>16,816.68</b>  | <b>2,601.07</b>   | <b>14,215.61</b>  | <b>84.53</b>  |

**INSPECTION**

|                             |            |               |                                   |
|-----------------------------|------------|---------------|-----------------------------------|
| Date of Assignment:         | 09/01/2023 |               | Premium Automobiles Pte Ltd (UBI) |
| Date Inspected:             | 06/01/2023 | Inspected At: | 55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 4.0 days   |               |                                   |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                                | Repair        | 1,677.00 FS | *- FS      |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                   | Not Necessary | 290.00 FS   | *- FS      |
| 3   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LH           | Not Necessary | 130.00 FS   | *- FS      |
| 4   | 1   |          | *FRONT BUMPER GRILLE - LOWER CENTRE          | Not Necessary | 433.00 FS   | *- FS      |
| 5   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Not Necessary | 265.00 FS   | *- FS      |
| 6   | 1   |          | *FRONT BUMPER AIR GUIDE - LH                 | Not Necessary | 67.00 FS    | *- FS      |
| 7   | 1   |          | *FRONT BUMPER TRIM COVER - LH                | Not Necessary | 104.00 FS   | *- FS      |
| 8   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH          | Cut           | 171.00 FS   | *136.40 FS |
| 9   | 1   |          | *FRONT PARKING AID SENSOR BRACKET - LH       | Not Necessary | 43.00 FS    | *- FS      |
| 10  | 1   |          | *FRONT BUMPER GUIDE SECTION - LH             | Not Necessary | 54.00 FS    | *- FS      |
| 11  | 1   |          | *FRONT BUMPER COVER                          | Not Necessary | 93.00 FS    | *- FS      |
| 12  | 1   |          | *CAUTION SIGN STICKER                        | Not Necessary | 16.00 FS    | *- FS      |
| 13  | 1   |          | *AIR CONDITIONER STICKER                     | Not Necessary | 9.00 FS     | *- FS      |
| 14  | 1   |          | *FRONT PARKING AID SENSOR - OUTER            | Not Necessary | 279.00 FS   | *- FS      |
| 15  | 1   |          | *FRONT PARKING AID SENSOR - LH               | Not Necessary | 266.00 FS   | *- FS      |
| 16  | 4   |          | *FRONT PARKING AID SEAL RING                 | Not Necessary | 52.00 FS    | *- FS      |
| 17  | 1   |          | *FRONT FENDER - LH                           | Repair        | 1,241.00 FS | *- FS      |
| 18  | 3   |          | *FRONT FENDER RIVET                          | Not Necessary | 12.00 FS    | *- FS      |
| 19  | 1   |          | *FRONT FENDER CLOSING ELEMENT - LH           | Not Necessary | 32.00 FS    | *- FS      |
| 20  | 1   |          | *FRONT FENDER BRACKET - LH                   | Not Necessary | 46.00 FS    | *- FS      |
| 21  | 1   |          | *FRONT FENDER BRACKET - LH                   | Not Necessary | 35.00 FS    | *- FS      |
| 22  | 1   |          | *FRONT FENDER BRACE - LH                     | Not Necessary | 98.00 FS    | *- FS      |
| 23  | 1   |          | *FRONT WHEEL HOUSING LINER - LH              | Not Necessary | 183.00 FS   | *- FS      |
| 24  | 1   |          | *FRONT FENDER CLOSING ELEMENT - LH           | Not Necessary | 22.00 FS    | *- FS      |
| 25  | 1   |          | *HEALDIGHT - LH                              | Not Necessary | 4,084.00 FS | *- FS      |
| 26  | 1   |          | *HEADLIGHT HOSE - LH                         | Not Necessary | 28.00 FS    | *- FS      |
| 27  | 1   |          | *LIFT CYLINDER - LH                          | Not Necessary | 211.00 FS   | *- FS      |
| 28  | 1   |          | *LIFT CYLINDER HOSE                          | Not Necessary | 108.00 FS   | *- FS      |
| 29  | 1   |          | *SUNDRIES                                    | Not Necessary | 400.00 FS   | *- FS      |

F=Franchise part. S=SpcNett.

**Total Parts (\$)**    **10,449.00**    **136.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                     | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                 |          |                 |                 |
| 1                              | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New      | 480.00          | 480.00          |
| 2                              | TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE                                                                             | New      | 350.00          | 0.00            |
| 3                              | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED   | New      | 2,100.00        | 500.00          |
| 4                              | TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER                                                                                                    | New      | 2,000.00        | 1,100.00        |
| 5                              | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                   | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                 |          | <b>5,122.00</b> | <b>2,272.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >