

ALG.

1. Others

The U/C / Chassis frame / Body Structure affected due to collision.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0008/2023/EQ
DATE : 6-Jan-23
WIP : 57780

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LEOW KWEE HAR
ADDRESS : 1 ELIAS GREEN
#12-03
SINGAPORE 519959
TELEPHONE : HP +65 98288117
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220144895
VEHICLE NO : **SLB 6322 D**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 15/12/2022
ENGINE NO : DFY 321661
CHASSIS NO : WAUZZZGY4NA049066
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jan-23
PLACE OF ACCIDENT : 8@TRADEHUB 21 CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 6322 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	✗
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	5,122.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 6322 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,677.00	Ry
2	FRONT BUMPER FIXING PARTS	1	\$ 290.00	X
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 130.00	✓
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 433.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 265.00	X
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 67.00	X
7	FRONT BUMPER TRIM COVER - LH	1	\$ 104.00	X
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	int ✓
9	FRONT PARKING AID SENSOR BRACKET - LH	1	\$ 43.00	X
10	FRONT BUMPER GUIDE SECTION - LH	1	\$ 54.00	X
11	FRONT BUMPER COVER	1	\$ 93.00	X
12	CAUTION SIGN STICKER	1	\$ 16.00	✓
13	AIR CONDITIONER STICKER	1	\$ 9.00	✓
14	FRONT PARKING AID SENSOR - OUTER	1	\$ 279.00	X
15	FRONT PARKING AID SENSOR - LH	1	\$ 266.00	X
16	FRONT PARKING AID SEAL RING	4	\$ 52.00	X
17	FRONT FENDER - LH	1	\$ 1,241.00	Ry
18	FRONT FENDER RIVET	3	\$ 12.00	✓
19	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 32.00	✓
20	FRONT FENDER BRACKET - LH	1	\$ 46.00	X
SUB TOTAL SPARE PARTS		:	\$ 5,280.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 6322 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH	1	\$ 35.00	×
22	FRONT FENDER BRACE - LH	1	\$ 98.00	×
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00	×
24	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 22.00	×
25	HEADLIGHT - LH	1	\$ 4,084.00	×
26	HEADLIGHT HOSE - LH	1	\$ 28.00	×
27	LIFT CYLINDER - LH	1	\$ 211.00	×
28	LIFT CYLINDER HOSE	1	\$ 108.00	×
29	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 10,449.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	
GRAND TOTAL		:	\$ 15,571.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
Not Authorise Ex: H69
6/1/23 @ 220 pm
Resurvey before paint
4 days
Tanpin @ 11:00 am

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT