



## Final Report

Estimate No. : **b1 64603**  
Date Estimated : **06/01/2023**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Michelle Tan Geok Hoon (Chen Yuefen)**  
**99 Pemimpin Place**

**Singapore 576096**

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
<b>SMU7854S</b>	<b>WBA2X920407F85470</b>	<b>28/08/2020</b>	<b>216i Active Tourer</b>	<b>48164</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include making good the tailgate and knocking out dents caused by the accident	1,275.00	0.00	1,275.00
To spray paint rear bumper and tailgate	1,972.00	0.00	1,972.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	505.35	1.00	0.00	505.35
REAR BUMPER TRIM STRIP (BLACK)	105.30	1.00	0.00	105.30
REAR BUMPER PANEL PRIMED (LINES PDC)	1,088.30	1.00	0.00	1,088.30
LETTERING 216 I	65.60	1.00	0.00	65.60
PLAQUE 74MM	72.85	1.00	0.00	72.85

**# SUPPLEMENTARY ITEMS**

Total Labour :	3,663.00
Total Parts :	1,837.40
Total Labour & Parts (before GST) :	5,500.40
Deduction for Excess :	
Total Repair Costs less Excess:	5,500.40
GST @8%:	440.03
Grand Total :	5,940.43

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

