

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 23 Feb 2023

**Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SJP4003M  | Accident Date           | : 03/01/2023 |
| TP Vehicle No      | : SMP9535B  | Assignment Date         | : 09/01/2023 |
| Make               | : TOYOTA SIENTA   | Est. Duration of Repair | : 5          |
| Date of Inspection | : 05/01/2023  |                         |              |
| Inspection At      | : TSR AUTOMOTIVE PTE LTD (HQ)<br>160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY<br>SINGAPORE 575722 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,505.16 |
| Revised Amount              | :S\$ | 5,177.53  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 5,177.53  |
| Lump Sum Repair             | :S\$ | 4,100.00  |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.