Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

ECICS Limited To: From: LKK Auto Consultants Pte Ltd

10 Eunos Road 8

#09-04A Singapore Post Centre

Singapore 408600

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sharon Tan Chow Yen 19 Jan 2023 Date:

Preliminary Advice

Vehicle No : SJY2513Z Accident Date : 07/01/2023

: MPC22A00148500 Make : TOYOTA WISH Policy No.

Assignment Date : 09/01/2023 **Excess** : S\$0.00 Date of Inspection : 11/01/2023 Est. Duration of Repair : 7 DAYS

Inspection At : KAN FOOK SING MOTOR WORKSHOP

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,469.80 (Est \$7,200.30 + Supp \$269.50)
Revised Amount	:S\$	6,831.30 (Rev \$6,561.80 + Supp \$269.50)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,831.30

:S\$

Total Loss Consideration

Lump Sum Repair

New for Old Value	:S\$	
Pre-Accident Value	:S\$	26,000.00
COE / PARF Rebate	:S\$	8,112.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,888.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly I	et
	us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approve on Revise items and Supplementary. Part by Part repair. According to the repairer, there are no second-hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check,part prices and labour cost.