

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 11 Apr 2023

Preliminary Advice

Vehicle No	: SJY2513Z	Accident Date	: 07/01/2023
Make	: TOYOTA WISH	Policy No.	: MPC22A00148500
Assignment Date	: 09/01/2023	Excess	: S\$0.00
Date of Inspection	: 11/01/2023	Est. Duration of Repair	: 7 days
Inspection At	: KAN FOOK SING MOTOR WORKSHOP		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,530.30	(Est \$7,200.30 + 1st Supp \$269.50 + 2nd Supp \$60.50)
Revised Amount	:S\$	6,381.40	(Inclu 1st & 2nd Supp \$330.00)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	6,381.40	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	26,000.00
COE / PARF Rebate	:S\$	8,112.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,888.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Revise items and Supplementary.Part by Part repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.