



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	-	Date of Loss:	07/01/2023
Vehicle Reg. No.:	SJY2513Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TOO TEH HSIN		
Make/Model:	TOYOTA WISH, 2.0 (A)	Vehicle Reg. Date:	16/08/2010
Vehicle Colour:	METALLIC BLUE		
Engine No:	3ZRA491776	Chassis No:	JTDGJ20W305002551
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS	Amount
Parts	5,030.30
C Miscellaneous Items	140.00
Labour	1,050.00
Paintwork Labour	980.00
Towing	0.00
Gross Total (S\$)	7,200.30
+ GST 8.00% (S\$)	576.02
Nett Amount (S\$)	7,776.32

This claim is handled by: MT TAN

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jan 2023)
Parts:	N/A TOYOTA WISH 2.0 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>Deleted</i>	0.00	0.00	*300.00 F ✓
2	1		*FRONT BONNET LOCK <i>Deleted</i>	0.00	0.00	*40.00 F ✓
3	1		*FRONT BONNET HINGE RH <i>Best</i>	0.00	0.00	*35.00 F ✓
4	1		*FRONT BONNET HINGE LH <i>Best</i>	0.00	0.00	*35.00 F ✓
5	1		*FRONT BONNET INSULATOR <i>new torn</i>	0.00	0.00	*160.00 F ✓
6	10		*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*25.00 F ✓
7	1		*FRONT SUPPORT PANEL <i>Deleted</i>	0.00	0.00	*480.00 F ✓
8	1		*FRONT SUPPORT TOP GARNISH <i>Deleted</i>	0.00	0.00	*45.00 F ✓
9	8		*FRONT SUPPORT TOP GARNISH CLIP <i>new</i>	0.00	0.00	*20.00 F ✓
10	1		*FRONT BRACE PANEL <i>Deleted</i>	0.00	0.00	*40.00 F ✓
11	1		*FRONT GRILLE <i>Deleted</i>	0.00	0.00	*75.00 F ✓
12	1		*FRONT FENDER RH <i>Deleted</i>	0.00	0.00	*260.00 F ✓
13	1		*FRONT FENDER LH <i>Deleted</i>	0.00	0.00	*260.00 F ✓
14	1		*FRONT FENDER SHIELD RH <i>new</i>	0.00	0.00	*80.00 F ✓
15	1		*FRONT FENDER SHIELD LH <i>new</i>	0.00	0.00	*80.00 F ✓
16	20		*FRONT FENDER SHIELD CLIP <i>new</i>	0.00	0.00	*50.00 F ✓
17	1		*FRONT HEADLAMP RH <i>new</i>	0.00	0.00	*330.00 F ✓
18	1		*FRONT HEADLAMP LH <i>new</i>	0.00	0.00	*330.00 F ✓
19	1		*FRONT BUMPER <i>Deleted</i>	0.00	0.00	*280.00 F ✓
20	1		*FRONT BUMPER SIDE RETAINER RH <i>Deleted</i>	0.00	0.00	*30.00 F ✓
21	1		*FRONT BUMPER SIDE RETAINER LH <i>Deleted</i>	0.00	0.00	*30.00 F ✓
22	1		*FRONT BUMPER FOAM <i>Deleted</i>	0.00	0.00	*40.00 F ✓
23	1		*FRONT BUMPER REINFORCEMENT <i>Deleted</i>	0.00	0.00	*110.00 F ✓
24	1		*FRONT BUMPER FOGLAMP COVER LH <i>new</i>	0.00	0.00	*40.00 F ✓
25	1		*FRONT BUMPER FOGLAMP INNER GRILLE LH <i>new</i>	0.00	0.00	*40.00 F ✓
26	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	*25.00 F ✓
27	1		*AIR CON CONDENSER <i>wrapped</i>	0.00	0.00	*270.00 F ✓
28	1		*AIR CON SIDE GARNISH RH <i>Deleted</i>	0.00	0.00	*35.00 F ✓
29	1		*AIR CON SIDE GARNISH LH <i>Deleted</i>	0.00	0.00	*35.00 F ✓
30	1		*RADIATOR <i>Deleted</i>	0.00	0.00	*480.00 F ✓
31	1		*RADIATOR TOP HOSE <i>Deleted</i>	0.00	0.00	*28.00 F ✓
32	1		*RADIATOR FAN COWLING <i>Deleted</i>	0.00	0.00	*90.00 F ✓
33	1		*RADIATOR FAN BLADE <i>Deleted</i>	0.00	0.00	*65.00 F ✓
34	1		*RADIATOR FAN MOTOR <i>Deleted</i>	0.00	0.00	*170.00 F ✓
35	1		*RADIATOR TOP GARNISH <i>Deleted</i>	0.00	0.00	*40.00 F ✓
36	1		*SPARE TANK <i>Deleted</i>	0.00	0.00	*75.00 F ✓
37	1		*WASHER TANK <i>new</i>	0.00	0.00	*45.00 F ✓

F=Franchise part.

Sub Total (S\$)	4,573.00
+ Margin on L,N Items 10.00% (S\$)	457.30
Total Parts (S\$)	5,030.30

Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			30.
1	1	ALARM <i>amend</i>	100.00 30.
2	1	FRONT NUMBER PLATE <i>Beat -</i>	40.00 40.00
Sub Total (S\$)			140.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	980.00 900
<u>Labour Items</u>			
2	TO CHECK WIING SYSTEM	New	50.00 30.
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00 100
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING	New	880.00 800
	NEW PARTS		
Gross Labour Cost (S\$)			2,030.00

Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Adrian Cg
P/P 11/01/23.

07 Days.

Not Authorised

Excess : \$600.

Resurveyed Before
Paint 17/01/23.
S.S.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC22A00148500	Date of Loss:	07/01/2023
Vehicle Reg. No.:	SJY2513Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TOO TEH HSIN		
Make/Model:	TOYOTA WISH, 2.0 (A)	Vehicle Reg. Date:	16/08/2010
Vehicle Colour:	Metallic Blue		
Engine No:	3ZRA491776	Chassis No:	JTDGJ20W305002551
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	269.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	269.50
+ GST 8.00% (S\$)	21.56
Nett Amount (S\$)	291.06
+ Previous Estimates (S\$)	7,776.32
Claim Total (S\$)	8,067.38

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Jan 2023)
Parts: N/A TOYOTA WISH 2.0 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SJY2513Z/16/01/2023 12:43
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON FAN BLADE <i>Damaged</i>	0.00	0.00	*80.00 F
2	1		*AIR CON FAN MOTOR <i>Damage d</i>	0.00	0.00	*165.00 F
Sub Total (S\$)						245.00
+ Margin on L,N Items 10.00% (S\$)						24.50
Total Parts (S\$)						269.50

F=Franchise part.

Kan Fook Sing Motor Workshop/SJY2513Z/16/01/2023 12:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SJY2513Z/16/01/2023 12:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >