

RFS Motor

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987
VEHICLE NO. : SJY2513Z
ACCIDENT DATE : 07-01-2023 13:45
THIRD PARTY REF. : UNKNOWN

INVOICE NO : TEST
DATE : 19-01-2023

ATTN: ECICS LIMITED

INVOICE COST OF REPAIRS TO VEHICLE SJY2513Z TOYOTA WISH 2.0 AUTO

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BONNET	300.00
1	FRONT BONNET LOCK	40.00
2	FRONT BONNET HINGE@\$35.00	70.00
6	FRONT BONNET INSULATOR CLIP@\$1.50	9.00
1	FRONT SUPPORT PANEL	480.00
8	FRONT SUPPORT TOP GARNISH CLIP@\$2.50	20.00
1	FRONT BRACE PANEL	40.00
1	FRONT GRILLE	75.00
2	FRONT FENDER@\$260.00	520.00
2	FRONT HEADLAMP@\$330.00	660.00
1	FRONT BUMPER	280.00
2	FRONT BUMPER SIDE RETAINER@\$30.00	60.00
1	FRONT BUMPER FOAM	40.00
1	FRONT BUMPER REINFORCEMENT	110.00
1	FRONT BUMPER FOGLAMP INNER GRILLE LH	35.00
10	FRONT BUMPER CLIP@\$2.50	25.00
1	AIR CON CONDENSER (OEM)	80.00
1	RADIATOR TOP HOSE	20.00
1	RADIATOR FAN COWLING	90.00
1	RADIATOR FAN BLADE	65.00
1	RADIATOR FAN MOTOR	170.00
1	RADIATOR TOP GARNISH	40.00
1	SPARE TANK	75.00
1	Radiator	\$160
1	Bonnet Insulator	\$160
1	Front bumper Foglamp inner grille LH	\$35

VEHICLE NO. : SJY2513Z
ACCIDENT DATE : 07-01-2023 13:45
THIRD PARTY REF. : UNKNOWN

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	WASHER TANK	45.00
1	RADIATOR LOWER HOSE	20.00 *
1	AIR CON FAN BLADE	80.00 *
1	AIR CON FAN MOTOR	165.00 *
		3969.00
		396.90
		4365.90

ADD 10 %

TOTAL (A)

SPECIAL NETT ITEMS

1	ALARM	30.00
1	FRONT NUMBER PLATE	40.00
		TOTAL (C)
		70.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE/REFIT/REFILL AIR CON GAS	100.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	800.00
1	SPRAYPAINTING CHARGES	900.00
		TOTAL (D)
		1,830.00
		TOTAL REPAIR COST :
		6265.90
		G S T % :
		501.27
		INVOICE AMOUNT :
		6767.17

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Jan 2023)

Parts: N/A TOYOTA WISH 2.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET <i>Deled</i>	0.00	0.00	*300.00F	✓
2	1		*FRONT BONNET LOCK <i>Deled</i>	0.00	0.00	*40.00F	✓
3	1		*FRONT BONNET HINGE RH <i>? Best</i>	0.00	0.00	*35.00F	✓
4	1		*FRONT BONNET HINGE LH <i>? Best</i>	0.00	0.00	*35.00F	✓
5	1		*FRONT BONNET INSULATOR <i>new form</i>	0.00	0.00	*160.00F	✓
6	10		*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*25.00F	✓
7	1		*FRONT SUPPORT PANEL <i>Broken</i>	0.00	0.00	*480.00F	✓
8	1		*FRONT SUPPORT TOP GARNISH <i>Deled</i>	0.00	0.00	*45.00F	✓
9	8		*FRONT SUPPORT TOP GARNISH CLIP <i>new</i>	0.00	0.00	*20.00F	✓
10	1		*FRONT BRACE PANEL <i>Best</i>	0.00	0.00	*40.00F	✓
11	1		*FRONT GRILLE <i>new</i>	0.00	0.00	*75.00F	✓
12	1		*FRONT FENDER RH <i>Deled</i>	0.00	0.00	*260.00F	✓
13	1		*FRONT FENDER LH <i>Broken</i>	0.00	0.00	*260.00F	✓
14	1		*FRONT FENDER SHIELD RH <i>? new</i>	0.00	0.00	*89.00F	✓
15	1		*FRONT FENDER SHIELD LH <i>? new</i>	0.00	0.00	*89.00F	✓
16	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	*50.00F	✓
17	1		*FRONT HEADLAMP RH <i>? new</i>	0.00	0.00	*330.00F	✓
18	1		*FRONT HEADLAMP LH <i>? new</i>	0.00	0.00	*330.00F	✓
19	1		*FRONT BUMPER <i>Deled</i>	0.00	0.00	*280.00F	✓
20	1		*FRONT BUMPER SIDE RETAINER RH <i>Deled</i>	0.00	0.00	*30.00F	✓
21	1		*FRONT BUMPER SIDE RETAINER LH <i>Deled</i>	0.00	0.00	*30.00F	✓
22	1		*FRONT BUMPER FOAM <i>new</i>	0.00	0.00	*40.00F	✓
23	1		*FRONT BUMPER REINFORCEMENT <i>Deled</i>	0.00	0.00	*110.00F	✓
24	1		*FRONT BUMPER FOGLAMP COVER LH <i>? new</i>	0.00	0.00	*40.00F	✓
25	1		*FRONT BUMPER FOGLAMP INNER GRILLE LH <i>? new</i>	0.00	0.00	*40.00F	✓
26	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	*25.00F	✓
27	1		*AIR CON CONDENSER <i>wrapped</i>	0.00	0.00	*270.00F	✓
28	1		*AIR CON SIDE GARNISH RH <i>? Deled</i>	0.00	0.00	*35.00F	✓
29	1		*AIR CON SIDE GARNISH LH <i>? Deled</i>	0.00	0.00	*35.00F	✓
30	1		*RADIATOR <i>Deled</i>	0.00	0.00	*480.00F	✓
31	1		*RADIATOR TOP HOSE <i>new</i>	0.00	0.00	*28.00F	✓
32	1		*RADIATOR FAN COWLING <i>new</i>	0.00	0.00	*90.00F	✓
33	1		*RADIATOR FAN BLADE <i>new</i>	0.00	0.00	*65.00F	✓
34	1		*RADIATOR FAN MOTOR <i>Deled</i>	0.00	0.00	*170.00F	✓
35	1		*RADIATOR TOP GARNISH <i>new</i>	0.00	0.00	*40.00F	✓
36	1		*SPARE TANK <i>Deled</i>	0.00	0.00	*75.00F	✓
37	1		*WASHER TANK <i>? new</i>	0.00	0.00	*45.00F	✓

F=Franchise part.

Sub Total (\$\$) 4,573.00
+ Margin on L,N Items 10.00% (\$\$) 457.30
Total Parts (\$\$) 5,030.30

Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			30.
1	1	ALARM <i>2nd</i>	100.00
2	1	FRONT NUMBER PLATE <i>Beut</i>	40.00
Sub Total (\$\$)			140.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	980.00 900
<u>Labour Items</u>			
2	TO CHECK WING SYSTEM	New	50.00 30
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00 100
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	880.00 800
Gross Labour Cost (\$\$)			2,030.00

Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Adrian C
P/P 11/01/23.

07 Days.

Not Authorised

Excess : \$600.

Resurveyed Before
Paint 17/01/23.

Sl/s

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Jan 2023)
 Parts: N/A TOYOTA WISH 2.0 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SJY2513Z/16/01/2023 12:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON FAN BLADE <i>Damaged</i>	0.00	0.00	*80.00 F
2	1		*AIR CON FAN MOTOR <i>Damaged</i>	0.00	0.00	*165.00 F
Sub Total (S\$)						245.00
+ Margin on L,N Items 10.00% (S\$)						24.50
Total Parts (S\$)						269.50

F=Franchise part.

Kan Fook Sing Motor Workshop/SJY2513Z/16/01/2023 12:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hereby notify the Repairer of the following:

- To remedy before after spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action will be allowed
- Suppliers are required to be recovered and is subject to third party audit by Insurance Company

Acknowledged by Repairer

Signature

Date

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Apr 2023)

Parts: N/A TOYOTA WISH 2.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SJY2513Z/06/04/2023 11:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER FOG LAMP INNER GRILLE RH	0.00	0.00	*35.00 F
2	1		*RADIATOR LOWER HOSE	0.00	0.00	*20.00 F

F=Franchise part.

Sub Total (\$\$)	55.00
+ Margin on L,N Items 10.00% (\$\$)	5.50

Total Parts (\$\$)	60.50
--------------------	-------

Kan Fook Sing Motor Workshop/SJY2513Z/06/04/2023 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SJY2513Z/06/04/2023 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >