

(08/1/13) wef

ASS. REC. BY: Ram

REF:

CS/AG123000210/Rgy3

4642

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JUS 1416at Workshop m/s Km Kockof 27A, Jurong Park Rd #01-19Insured: AGI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 5K(est)

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

16/05/23 Submit Uneconomical Total Loss report.

MV:\$5K(est); LTA:\$0/-; NV:\$5K

Veh No: JUS 1416 Yr Regn: 2021 / gnh

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Wmoto RT3 C.C. 247Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 24339 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PRS2RT25BMA000192

Gen. Cond: Good / Fair / Poor / Burnt

Steering: order / Jammed / Leaked / Burnt orBrake: order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-15R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TIMSUN

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 29/12/22 D.O.I. 10/01/23Survey held at Km KockDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1) 16/05 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS, SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : TP-T/L-U

Lump Sum / I.B.I: (\$ _____)

JUS 1416 Terib 2563561 ①
Lkk

(Kasul)

R/L Front Fork Assy — \$780 — bt —
#P 9090068

Front Spoling Assy — \$395 — cm —

To Wing To TP — \$60 —

Front Brake disc — \$195 — cm —

Rim shaft 1 pc — \$48 — / nec

Front Fork under bracket \$380 — bt —

Com Beding Assy — \$130 — bt —

Front Mudguard — \$98 — cm —

Handle Bar Assy — \$145 — bt —

Handle Grip R/L — \$38 — ms —

R/L Handle Bar Belesen — \$58 — sec —

Head light Assy — \$480 — bro —

Head Cowling R/L — \$490 — cm —

Head Cowling Centra Wiskem — \$295 — cm —

Number Plate Front — \$28 — s/n 20BT

Front MIRROR R/L — \$190 — cm —

Wiskem R/L COVER — \$48 — sec —

Brake lever R/L — \$130 — sec —

Signal Front R/L — \$190 — cm —

(2)

Chassis - Body Assy — \$1950 - bt -

Meter Assy — \$595 - cr -

Meter Cover — \$95 - cr -

(Black) - WINKIN IN COVER — \$168 - sc -

Front Central Bracket — \$295 - bt -

Radiator Assy — \$490 - bt -

Radiator Cover — \$85 - bt -

Handle Bar Lower Cover \$95 - cr -

Fan & Motor Assy — \$380 - cr -

Body Central Cover Big \$295 - cr -

Key Central Cover — \$155 - cr -

(L) Tool Box Cover — \$58 - cr -

Seat Front Cover — \$145 - cr -

R/L - Head light Central Cover — \$190 - cr -

5 PC - Lower Failing Assy \$690 - cr -

Under Failing — \$195 - cr -

6 PC - Side Failing R/L — \$850 - cr -

Front - Foot Rest Cover R/L — \$360 - sc -

SIDE STAM — ~~#~~ 135.61/

③

MISER ASSY — ~~#~~ 155.61/

(L) BEITING BOX COVER ~~#~~ 95.50 ✓

(L) REAR SIDE FALING — ~~#~~ 295.00 ✓
ABS SENSOR FRONT — ~~#~~ 85.00 ✓

(Blue) - Central Body Faling R/L ~~#~~ 290.00 X_{NN}

AJER PIPE ASSY — ~~#~~ 590.00 ✓

REAR KAPPA BOX — ~~#~~ 165.00 ✓

LABUAR — ~~#~~ 380.00 3.00

Resu
Hp 900 w068

7 days

P/P

~~#~~ 13459.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resy before repair



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

SYT8V7HW

No. Pendaftaran : JUS1416
No. ID : 780415105171
Nama Pemunya Berdaftar : TEE TIAN KOK
Alamat : NO 04-02 BLOK Q JALAN CENDERAI 19 RIA APT TAMAN
MEGAH RIA
81750 MASAI JOHOR
No. Chasis/No. Enjin : PRSZRT25BMA000192 / WM1P73MM-S5M400120
Buatan>Nama Model : WMOTO / RT3
Keupayaan Enjin : 247
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2021
Tarikh Pendaftaran : 05/08/2021
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



16648408

扫描全能王 创建



NOTA PENTING

1. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
2. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
3. Jika alamat anda bertukar, sila kemaskini dalam tempoh dua bulan dari tarikh pertukaran ini.