

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Yang Su
332 Tah Ching Road
#02-179

Singapore 610332

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Yang Su

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 05/01/2023
WIP No. . : 57816
Veh.In/Out: 05/01/2023
*Tel.No. . : Mobile: 98258383
Reg.No. . : SLU3070A
Reg.date . : 13/01/2015
Mileage .. : 0
Chassis No: YV1MZ845BF2067684

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT RH FENDER,FRT RH DOOR,FRT RH WING MIRROR,ETC	0	3400.00	0		3,400.00	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER,FRT RH FENDER,FRT RH DOOR,ETC	0	3750.00	0		3,750.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	555.00	0		555.00	S
	MIRROR BACK COVER RH	1.0 EA	488.00			488.00	S
	DOOR MIRROR RH (E) V	1.0 EA	780.10			780.10	S
	MIRROR GLASS RH S60	1.0 EA	328.80			328.80	S
	BUMPER MOULDING RH V	1.0 EA	262.10			262.10	S
	BLIND RIVET 4.0*21 P	10.0 EA	5.20			52.00	S
	BUMPER CLIP XC90 16-	1.0 EA	8.80			8.80	S
	D PAINT PRIMER 30m	1.0 EA	102.70			102.70	S

Gross Total. 9,727.50

Labour Total	7,705.00	Net.....	9,727.50
Parts Total	2,022.50	GST @ 8.0%	778.20
Package Total	0.00	Total.....	10,505.70
		Paid.....	0.00
		Please Pay..	10,505.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate