

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 10-Dec-22

INSURANCE: MSIG

MODEL: BMW

VEHICLE NO.: SLV 4517 S

DESCRIPTION	QTY	UNIT PRICE	NETT PRICE
REAR BUMPER	1		\$1,384.55
REAR BUMPER REINFROCEMENT	1		\$577.45
REAR BUMPER LOWER GARNISH	1		\$189.56
REAR BUMPER SENSOR	2	\$285.55	\$571.10
SUB TOTAL			\$2,722.66
LESS 0%			
DISCOUNTED TOTAL			
SUB TOTAL			\$0.00
Labour Charge			
Panel Beating	1	\$300.00	\$300.00
check rear wring & replace sensor	1	\$80.00	\$80.00
Spray Painting Charge	1	\$400.00	\$400.000
TOTAL LABOUR			\$780.00
ESTIMATE TOTAL			\$3,502.66

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.