

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyo

Date: 31 Jan 2023

Preliminary Advice

Insured Vehicle No	: SP71K	Accident Date	: 10/12/2022
TP Vehicle No	: SLV4517S	Assignment Date	: 10/01/2023
Make	: BMW 316I	Est. Duration of Repair	: 2
Date of Inspection	: 10/01/2023		
Inspection At	: BIFROST AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #03-09 SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,502.66
Revised Amount	:S\$	1,894.55
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,894.55

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis. :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.