

ASS. REC. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SVV8998J Yr Regn: 2016 Dec.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andi A4 C.C. 1395

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 113459 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F46HA025175

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 11/01/23

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Lon Pac</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett.</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

Report Format: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0026/2023/EQ
DATE : 11-Jan-23
WIP : 58075

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/2023
YOUR INSURED VEH NO : XE 3952 Y

Lonpac Insurance BHD

300 Beach Road

#17-04/07, The Concourse

Singapore 199555

Attn: Motor Claims Dept

OWNER'S NAME : MR CAROLINE CASSANDRA LEE LAN FUI
ADDRESS : APT BLK 487 C TAMPINES ST 45
#03-101
SINGAPORE 522487
TELEPHONE : HP +65 97431060
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : **SJV 8998 J**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 26/2/2021
ENGINE NO : CZD C28132
CHASSIS NO : WAUZZZF3XM1071416
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Jan-23
PLACE OF ACCIDENT : CAR PARK OF TAMPINES T81

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJV 8998]

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	✓ ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONRTOL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPOENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1400 ✓
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1600 1500 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 8,502.00	

✓

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 8998 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,515.00	<i>✓</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 641.00	<i>+</i>
3	FRONT BUMPER SECURING STRIP - LH / RH <i>?</i>	2	\$ 84.00	<i>XNN</i>
4	FROTN BUMPER GRILLE - CENTER <i>new</i>	1	\$ 231.00	<i>+</i>
5	FRONT BUMPER CLOSING ELEMNT - LOWER CENTRE <i>new</i>	1	\$ 269.00	<i>+</i>
6	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 75.00	<i>+</i>
7	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,310.00	<i>✓</i>
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 159.00	<i>+</i>
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 147.00	<i>?</i> <i>X NN</i>
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 953.00	<i>?</i>
11	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 43.00	<i>+</i>
12	FRONT BUMPER TOP COVER <i>?</i>	1	\$ 151.00	<i>?</i>
13	CAUTION SIGN STICKER <i>?</i>	1	\$ 17.00	<i>?</i> <i>XNN</i>
14	AIR CONDITIONER STICKER <i>?</i>	1	\$ 9.00	<i>?</i>
15	FROTN BUMPER BRACKET <i>?</i> <i>Damaged</i>	1	\$ 163.00	<i>✓</i> <i>162.50</i>
16	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 68.00	<i>?</i> <i>X NN</i>
17	HORN LOW TONE - RH <i>new</i>	1	\$ 149.00	<i>+</i>
18	HORN BRACKET - RH <i>new</i>	1	\$ 35.00	<i>+</i>
19	BONNET <i>Dented</i>	1	\$ 3,489.00	<i>✓</i> <i>✓</i>
20	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 455.00	<i>+</i>
SUB TOTAL SPARE PARTS		:	\$ 10,963.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 8998 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - CENTER <i>3 new</i>	1	\$ 34.00 ✓	33.60
22	BONNET IMPACT PROTECTION - LH / RH	2	\$ 67.00 ✓	66.40
23	BONNET STRIKER - LH / RH <i>not new</i>	2	\$ 120.00 +	
24	BONNET LOCK - LH / RH <i>not new</i>	2	\$ 481.00 +	
25	BONNET BOWDEN CABLE <i>not new</i>	1	\$ 67.00 X	
26	BONNET RELEASE LEVER <i>not new</i>	1	\$ 16.00 +	
27	BONNET BOWDEN CABLE - CENTER <i>not new</i>	1	\$ 67.00 +	
28	BONNET RELEASE CABLE COVER <i>not new</i>	1	\$ 12.00 +	
29	FRONT FENDER LEDGE COVER - RH LONG <i>not new</i>	1	\$ 27.00 +	
30	HEADLIGHT - RH <i>lit</i>	1	\$ 8,787.00 ✓	✓
31	LIFT CYLINDER - RH <i>not new</i>	1	\$ 244.00 +	
32	LIFT CYLINDER CORRUGATED PIPE <i>3 new</i>	1	\$ 111.00 +	
33	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00 +	
34	RADIATOR AIR GUIDE - RH INNER <i>2</i>	1	\$ 38.00 +	
35	RADIATOR AIR GUIDE - LH / RH OUTER <i>✓ CRA</i>	2	\$ 50.00 ✓	24.90
36	RADIATOR AIR GUIDE - UPPER	1	\$ 25.00 +	
37	RADIATOR AIR GUIDE - LOWER <i>not new</i>	1	\$ 38.00 +	
38	INTAKE AIR DUCT - RH	1	\$ 38.00 +	
39	ENGINE AIR INTAKE HOSE	1	\$ 67.00 +	
40	INTAKE HOSE	1	\$ 114.00 +	
SUB TOTAL SPARE PARTS			\$ 10,425.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 8998 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	AIR FILTER	1	\$ 443.00	✓
42	LOCK CARRIER	1	\$ 1,569.00	✓
43	READY-MIX COOLANT	6	\$ 326.00	✓
44	FRONT NO PLATE	S/N	\$ 60.00	✓
45	SUNDRIES		\$ 400.00	✗
TOTAL SPARE PARTS		:	\$ 24,186.00	
TOTAL LABOUR CHARGES		:	\$ 8,502.00	
GRAND TOTAL		:	\$ 32,688.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *11/01/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT