

Our Job Ref No : 305541921
Date 09.01.23

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHC3669R

Date of Accident : 05.01.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A CHINA --- SND5407R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,900.00
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 10/1/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	---	—		
LTA Search Fee	\$26.75	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 06.01.23
 MODEL: Hyundai Ioniq
 VEHICLE NO.: SHC3669R

D.O.A 05.01.23

INSURANCE: CHINA

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	FRT BUMPER	10		\$ 481.10	/CRA
	FRT BUMPER CLIPS			\$ 22.00	/NEC
	FRT BUMPER CENTRE MOULDING			\$ 368.50	/SCR
	FRT BUMPER SIDE BRACKET LH			\$ 35.00	?ASVC
	HEADLAMP ASSY LH			\$ 2,110.30	/SCR
	FRT FOG LAMP GRILLE			\$ 93.45	/SCR
	FRT FOG LAMP RH			\$ 642.50	X500 /CRA
	SUB TOTAL			\$ 3,752.85	
	LESS 20%			\$ 750.57	
	DISCOUNTED TOTAL			\$ 3,002.28	
	SUB - TOTAL				NET NET NET
	<u>Labour Charge</u>				
	PANEL BEATING			\$ 400.00	350
	SPRAY PAINT			\$ 300.00	250
	WIRING CHARGE			\$ 50.00	30
	TUFF KOTE			\$ 50.00	30
	TOTAL LABOUR			\$ 800.00	
	ESTIMATE TOTAL			\$ 3,802.28	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NA2 LKK
 6/1/2023 1635
 L/S
 2 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: