

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Tel: 6269 9192 H/P: 9631 1712

Business Reg. No: 36463500B

M/s: MS FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877

Date: 17.01.2023

Motor Claim Dept

Vehicle number : XD 1796 A
Make/Model : ISUZU CYZ
Date of accident : 03.11.2022
Claim Type : TP Claim

Accident involving XD 1796 A & SHD 6078 X

Re: Estimate

- | | | |
|----|------|-----------------------|
| 1. | 1 PC | TAIL LAMP |
| 2. | 1 PC | TAIL LAMP BRACKET |
| 3. | 1 PC | REAR MUDGUARD |
| 4. | 1 PC | REAR MUDFLAT |
| 5. | 1 PC | REAR MUDGUARD BRACKET |
| 6. | 1 PC | REAR TYRE |

LKK Auto Consol. & Co. Pte. Ltd.
the Repairer of the following.
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	385.00	an
\$	600.00	bb-300
\$	800.00	bb-450
\$	50.00	th
\$	230.00	lt
\$	450 600.00	ab-80% SW 360

ISUZU DISCOUNT -15%

SUB TOTAL

WIRING SERVICES
LABOUR CHARGES
PUTTY & SPRAY PAINTING

Yours Faithfully,

TOTAL

李光華 摩 嘜 燒 焊
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

1415
15% - 1202.75
SW 360
1202.75
360
930
2168.75 = 7 LSP 1700, 3 days
Tang Hin 9741574 9/62563561
17/1/23 @ 12pm
L/S Resurvey after repair
Tang Hin C/Khau to n
3-4 days