

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23000306/Rvy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	15/03/2023	
	ATTN: HELENA TA	AN		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLL 7343J	Veh. Inspected	l	SLK 2958Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1204345-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		10/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTDKB3FU603542880	Colour		GREY	
	Odometer	412018 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DUNLOP		6 mm	
	L/H Front Tyre	195/65 R15	DUNLOP		6 mm	
	R/H Rear Tyre	195/65 R15	DUNLOP		6 mm	
	L/H Rear Tyre	195/65 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE D	ETAILS.				
5.						
	Accident Date	06/01/2023	Inspect Date /	Time	10/01/2023 (03:07 PM)	
	Survey held at	BORNEO MOTORS (S) PTE LT	D			
		2 PANDAN CRESCENT SINGAPORE 128462				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				