

ASS. REC-BY: T. G. J. M.

REF:

ALG

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: None

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9290K.

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGW 8335C

Yr Regn: 2022, DEC.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hindi E-Tron

C.C. 287 KW

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 1245

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W14227GE5 PB 000624

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 255 / 55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 6/1/23

Survey held at

Premium Auto.

Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

Photos _____

Others _____

Report Format: _____

Lump Sum / L.B. / L.P. _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0007/2023/EQ
DATE : 6-Jan-23
WIP : 57703

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS NAVPREET PUAR
ADDRESS : BLK 50 MARINE PARADE ROAD
#06-12
SINGAPORE 449307
TELEPHONE : HP +65 96841252
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SGW 8335 C**
MODEL CODE : AUDI E-TRON
MODEL YEAR : 16/12/2022
ENGINE NO : EAS 171562
CHASSIS NO : WAUZZZGE5PB000624
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jan-23
PLACE OF ACCIDENT : PIE, (GOING TOWARDS SLE) ON THE LANE TURNING TO SLE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGW 8335 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	X
3	TO CARRY OUT DE-ENERGISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACIVATION.	S/N \$	480.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,700.00	600
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00	650
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 6,802.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,896.00	Ry
2	FRONT BUMPER TRIM - LH / RH	2	\$ 130.00	X
3	FRONT BUMPER FIXING PARTS	1	\$ 658.00	X
4	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 248.00	X
5	FRONT BUMPER FOAM PART - LH	1	\$ 34.00	X
6	FRONT BUMPER SUPPPORT COVER - LH / RH	2	\$ 78.00	✓
7	FROTN BUMPER FOAM PART - UPPER	1	\$ 150.00	✓
8	FRONT BUMPER FOAM PART - LOWER	1	\$ 125.00	✓
9	FRONT BUMPER PLASTIC FOAM STRIP	1	\$ 134.00	X
10	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 283.00	✓
11	FRONT BUMPER GRILLE - CENTER	1	\$ 171.00	?
12	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 235.00	?
13	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 202.00	X
14	FRONT BUMPER IMPACT PROTECTION	1	\$ 899.00	X
15	FRONT BUMPER SPOILER - LH / RH	2	\$ 220.00	X
16	FRONT BUMPER AIR GUIDE - LH / RH OUTER	2	\$ 116.00	X
17	FRONT BUMPER AIR GUIDE - LH / RH INNER	2	\$ 90.00	X
18	RADIATOR AIR GUIDE - LH / RH	2	\$ 268.00	X
19	RADIATOR GRILLE	1	\$ 2,317.00	ma
20	RADIATOR GRILLE COVER CAP	1	\$ 141.00	?
SUB TOTAL SPARE PARTS		:	\$ 9,395.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE BRACKET	1	\$ 104.00	✗
22	RADIATOR GRILLE COVER	1	\$ 69.00	✗
23	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 246.00	✓
24	RADIATOR GRILLE COVER - LH / RH	2	\$ 122.00	✓
25	FRONT "360" CAMERA	1	\$ 1,006.00	✗
26	FRONT BUMPER WIRING SET	1	\$ 642.00	✗
27	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,451.00	✗
28	FRONT BUMPER SUPPORT BRACKET	1	\$ 481.00	✓
29	FRONT BUMPER BRACKET - LH / RH	2	\$ 174.00	✓
30	FRONT BUMPER SIGHT SHIELD	1	\$ 118.00	✓
31	FRONT BUMPER SIGHT SHIELD	1	\$ 119.00	✓
32	FRONT BUMPER GUIDE SECTION - LH	1	\$ 50.00	✓
33	CAUTION LABEL	1	\$ 23.00	✗
34	FRONT PARKING AID SENSOR - INNER	2	\$ 584.00	✓
35	FRONT PARKING AID SENSOR - OUTER	1	\$ 292.00	✓
36	FRONT PARKING AID SEAL RING	4	\$ 10.00	✗
37	FRONT SPOILER - LH / RH	2	\$ 212.00	✓
38	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 598.00	✓
39	RADIATOR AIR GUIDE BRAKE - LH / RH	2	\$ 100.00	✗
40	FRONT FENDER - LH	1	\$ 2,477.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,878.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 8335 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH	1	\$ 11.00	✓
42	FRONT FENDER BRACKET - CENTRE LH	1	\$ 15.00	✓
43	FRONT FENDER BRACKET - REAR	1	\$ 15.00	✓
44	FRONT FENDER BRACKET - LH	1	\$ 76.00	✓
45	FRONT FENDER BRACKET - LH INNER	1	\$ 18.00	✓
46	HEADLIGHT SEAL - LH	1	\$ 60.00	?
47	FRONT SUPPORT ELEMENT - LH	1	\$ 45.00	?
48	HEADLIGHT - LH	1	\$ 8,660.00	?
49	FRONT WHEEL COVER - LH / RH	2	\$ 648.00	see - photo
50	LIFT CYLINDER - LH / RH	2	\$ 518.00	✓
51	LIFT CYLINDER HOSE	1	\$ 111.00	✓
52	FRONT NO PLATE	S/N	\$ 60.00	ht -
53	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 29,010.00	
TOTAL LABOUR CHARGES		:	\$ 6,802.00	
GRAND TOTAL		:	\$ 35,812.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
Not Authorised Ex: +64
03 days 6/1/73 C245
Resurvey before paint
Tanpin C1hantowin

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT