

AUTOMOBILE HUB

VEHICLE DETAILS

VEHICLE NO : SJM9664M 2009 JAN
 VEHICLE MODEL : HONDA STREAM
 CHASSIS NO : RN61082880

nett 81k

TP Ego.
 Xin Yu

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT BUMPER <i>Deformed</i>		688.40	✓
2	FRONT BUMPER SIDE HOLDER @35.20 <i>new</i>		70.40	X.
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>		296.70	✓
4	FRONT BUMPER LOWER GRILLE <i>new</i>		145.40	X
5	FRONT BUMPER FOG LAMP COVER @65.20 <i>new</i>		130.40	X.
6	FRONT GRILLE <i>new</i>		259.40	✓
7	FRONT GRILLE CHROME MOULDING <i>new</i>		230.30	X
8	FRONT GRILLE LOGO <i>new</i>		48.90	✓
9	HEADLAMP @680.70 <i>LH cracked</i>		1361.40	680.70.
10	HEADLAMP LOWER BRACKET @45.90 <i>LH cracked</i>		91.80	45.90.
11	BONNET <i>Ryis</i>		761.90	X
12	BONNET LOCK <i>new</i>		98.10	X
13	BONNET HINGE @55.20 <i>new</i>		110.40	X
14	BONNET INSULATOR <i>new</i>		162.40	X.
15	FRONT SUPPORT PANEL <i>new</i>		566.50	X
16	FRONT SUPPORT PANEL TOP COVER <i>new</i>		167.40	X
17	FRONT FENDER @576.40 <i>new</i>		1152.80	X
18	HORN @76.2 <i>new</i>		152.40	X.
19	AIR CON CONDENSER <i>new</i>		1086.40	X
20	AIR CON FAN COWLING <i>new</i>		129.60	X
21	AIR CON FAN BLADE <i>new</i>		65.20	X
22	AIR CON FAN MOTOR <i>new</i>		356.40	X
23	RADIATOR <i>new</i>		1284.40	X
24	RADIATOR FAN COWLING <i>new</i>		139.20	X
25	RADIATOR FAN BLADE <i>new</i>		66.10	X
26	RADIATOR FAN MOTOR <i>new</i>		341.90	X
27	RADIATOR SPARE TANK <i>new</i>		94.70	X
28	RADIATOR TOP HOSE <i>new</i>		56.80	X.
29	REAR NUMBER PLATE LAMP @62.20 <i>new</i>		124.40	X
30	REAR BUMPER <i>Distorted</i>		668.40	✓
31	REAR BUMPER SIDE HOLDER @34.10 <i>new</i>		68.20	34.10.
32	REAR BUMPER TOW COVER <i>new</i>		39.40	X.
33	REAR END PANEL <i>Distorted</i>		459.10	✓
34	REAR END PANEL INNER MEMBER <i>Distorted</i>		186.90	✓
35	REAR END PANEL TOP GARNISH <i>Deformed</i>		216.70	✓
36	TAILLAMP @366.50 <i>LH smashed</i>		733.00	366.50
37	TAILLAMP PANEL @390.10 <i>LH dented</i>		780.20	390.10.
38	TAILGATE <i>Distorted</i>		903.40	✓

- 39 TAILGATE LOCK *Dmgd*
 40 TAILGATE WEATHERSTRIPE *at*
 41 TAILGATE DAMPER @212.10 *new*
 42 TAILGATE INNER TRIM BOARD *crackd*
 43 TAILGATE OUTER GARNISH *2*
 44 TAILGATE WIPER MOTOR *new*
 45 TAILGATE WIPER ARM *new*
 46 TAILGATE GLASS MOULDING *new*
 47 HONDA LOGO *new*
 48 STREAM WORDING *new*
 49 FLOOR PANEL *Reps*
 50 FLOOR PANEL TOP COVER @242.10 *LH Del-d*
 51 REAR FENDER @928.70 *LH Distorted*
 52 REAR FENDER INNER TRIM BOARD @295.40 *LH Del-d*
 53 REAR FENDER INNER SHIELD @80.10 *new*

7555
6044 less

SPECIAL NETT ITEMS

- 1 FRONT NUMBER PLATE *2 LH new*
 2 FRONT NUMBER PLATE HOLDER *new*
 3 FRONT BUMPER CLIPS *new*
 4 FRONT GRILLE CLIPS *new*
 5 BONNET INSULATOR CLIPS *new*
 6 FRONT SUPPORT PANEL TOP COVER CLIPS *new*
 7 COOLANT *new*
 8 REAR NUMBER PLATE *2 new*
 9 REAR NUMBER PLATE HOLDER *new*
 10 REAR BUMPER CLIPS *new*
 11 REVERSE SENSOR *Dmgd*
 12 REAR END PANEL TOP GARNISH CLIPS *new*
 13 REAR END PANEL SEALANT *new*
 14 TAILGATE INNER TRIM BOARD CLIPS *new*
 15 TAILGATE OUTER GARNISH CLIPS *new*
 16 TAILGATE INNER SIDE GARNISH CLIPS *new*
 17 TAILGATE GLASS SEALANT *new*
 18 FLOOR PANEL INSULATION PADS *new*
 19 REAR FENDER INNER TRIM CLIPS *new*
 20 REAR FENDER INNER SHIELD CLIPS *new*
 21 REAR FENDER GLASS SEALANT *new*

189.40 ✓
 195.90 ✓
 424.20 +
 285.10 ✓
 239.80 +
 361.90 +
 70.20 +
 124.10 ✓
 45.90 x.
 49.10 ✓
 1062.70 x.
 482.20 242.10.
 1857.40 928.70.
 590.80 295.40.
 160.20 x.

	20434.30		
20%	4086.86	20%	
	16347.44		
	30.00	x	
	30.00	x.	
	50.00	30.	
	20.00	✓	
	50.00	+	
	20.00	x	
	50.00	x	
	30.00	x	
	30.00	x.	
	50.00	30	
	280.00	200	
	20.00	✓	
	60.00	✓	
	30.00	✓	
	30.00	x	
	50.00	x.	
	60.00	✓	
	280.00	+	
	60.00	30	
	30.00	x	
	100.00	40.	
Total Parts	1360.00		

AUTOMOBILE HUB

SJM9664M

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	3400.00	1600
2	SPRAY PAINTING	2500.00	1400
3	WIRING	100.00	60
4	TO APPLY TUFF COAT	150.00	100
5	TO REMOVE UPHOLSTERY	150.00	60
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	X
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	X
8	TO REMOVE UPHOLSTERY	150.00	X.
9	TO TRANSFER TAILGATE FITTINGS	150.00	60
10	TO REMOVE TAILGATE GLASS	180.00	120
11	TO REMOVE REVERSE SENSOR	100.00	50
12	TO REMOVE FUEL TANK	150.00	60
13	TO REMOVE FENDER GLASSES	240.00	40
	Labour Total :	7510.00	
	TOTAL (PARTS & LABOUR):	25217.44	

3550

total: 10114

L/s: 81c (Nett)

13 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: