

ASS. REC. BY:

REF:

A15/ 23000312/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

BMW 1455P

Yr Regn:

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perault

(A) Wagon

c.c. 1496

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

153935

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1RFA00863699345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

Tundra 195/55R20

R: Triangle

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

1/1/23

D.O.I.

11/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

Days Of Repair:

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation

\$ - RS. \$

: P.A. \$

: Other \$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	01/01/2023
Vehicle Reg. No.:	SMW1455P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI	Vehicle Reg. Date:	04/11/2020
Vehicle Colour:	SR EU6 (A)		
Engine No:	RED	Chassis No:	VF1RFA00663699345
Engine No:	K9KF649D059983		
Odometer:	153935 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	<i>10 days</i>		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

*NOT Notified
Repair B4 paint
Ex @ 2000*

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	28,568.76
Labour	88.00
Paintwork Labour	4,100.00
Towing	0.00
	0.00
Calculated Gross Total (S\$)	32,756.76
- Excess (S\$)	2,000.00
(S\$)	30,756.76
+ GST 8.00% (S\$)	2,460.54
Nett Amount (S\$)	33,217.30

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jan 2023)
 Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SMW1455P/09/01/2023 18:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	631012967R	*FRONT FENDER RH	0.00	0.00	CM *673.00 F ✓
2	1	768B41643R	*FRONT FENDER QUARTER GLASS RH	0.00	0.00	*447.60 F 7
3	1	764190230R	*FRONT ROKER PANEL RH	0.00	0.00	R *564.70 F X
4	1	801004703R	*FRONT DOOR RH	0.00	0.00	A1 *2,094.00 F ✓
5	1	808773735R	*FRONT DOOR PROTECTOR RH	0.00	0.00	nu *572.70 F ✓
6	1	806061111R	*FRONT DOOR OUTER HANDLE RH	0.00	0.00	nu *172.00 F ✓
7	1	805023720R	*FRONT DOOR LOCK RH	0.00	0.00	R *424.20 F X
8	1	803308374R	*FRONT WINDOW MOULDING RH	0.00	0.00	nu *561.30 F ✓
9	1	804007634R	*FRONT DOOR HINGE RH UPP	0.00	0.00	A1 *220.30 F ✓
10	1	804218851R	*FRONT DOOR HINGE RH Low	0.00	0.00	A1 *220.30 F ✓
11	1	804301428R	*FRONT DOOR CHECK RH	0.00	0.00	*115.30 F 7
12	1	807200294R	*FRONT WINDOW REGULATOR RH	0.00	0.00	Tu *629.90 F ✓
13	1	241253698R	*FRONT WINDOW HARNESS WIRE RH	0.00	0.00	*289.50 F 7
14	1	803014736R	*FRONT WINDOW DOOR GLASS RH	0.00	0.00	CM *508.50 F ✓
15	1	809004434R	*FRONT DOOR TRIM RH	0.00	0.00	*958.20 F 7
16	1	803308374R	*FRONT DOOR WINDOW MOUNDING RH	0.00	0.00	Repon *561.30 F X
17	1	802841333R	*FRONT PILLAT DOOR TOP RH	0.00	0.00	CM *117.30 F 2
18	1	963010830R	*FRONT SIDE MIRROR RH	0.00	0.00	Ar *810.40 F ✓
19	1	822831642R	*REAR DOOR PILLAR TOP RH	0.00	0.00	CM *117.30 F ✓
20	1	828767411R	*REAR DOOR PROTECTOR RH	0.00	0.00	su *544.20 F X
21	1	400113779R	*FRONT KNUCKLE ARM RH	0.00	0.00	*587.80 F 7
22	1	402024EA1A	*FRONT W/HUB W/BRG RH	0.00	0.00	*594.80 F 7
23	1	391015778R	*FRONT DRIVER SHAFT	0.00	0.00	*1,151.80 F 7
24	1	545056560R	*FRONT LOWER ARM RH	0.00	0.00	*356.40 F 7
25	1	485216564R	*FRONT STEERING TIE ROD RH	0.00	0.00	*174.50 F 7
26	1	402064155R	*FRONT DISC ROTOR RH	0.00	0.00	*183.70 F 7
27	1	485206481R	*FRONT TIE ROD END RH	0.00	0.00	*174.50 F 7
28	1	490018113R	*FRONT STEERING RACK	0.00	0.00	*4,021.80 F 7
29	1	546188897R	*FRONT STABILISER LINK RH	0.00	0.00	*143.30 F 7
30	1	878163402R	*FRONT SEAT BELT TENSIONER RH	0.00	0.00	*210.90 F 7
31	1	878176089R	*FRONT SEAT BELT TENSIONER LH	0.00	0.00	*210.90 F 7
32	1	868854722R	*FRONT SEAT BELT LH	0.00	0.00	Tu *744.60 F 2
33	1	868841713R	*FRONT SEAT BELT RH	0.00	0.00	*744.60 F 7
34	1	888416952R	*REAR SEAT BELT 2ND ROW LH	0.00	0.00	Tu *948.20 F ✓
35	1	888404150R	*REAR SEAT BELT 2ND ROW RH	0.00	0.00	Tu *948.20 F ✓
36	1	985109965R	*AIR BAG COMPUTER UNIT	0.00	0.00	Re *1,397.60 F ✓
37	1	985L18614R	*FRONT SEAT AIR BAG RH	0.00	0.00	*1,130.30 F ✓
38	1	985P06802R	*FRONT ROOF SIDE BAG RH	0.00	0.00	*1,645.70 F ✓

F=Franchise part.

Sub Total (\$\$) 25,971.60
 + Margin on L,N Items 10.00% (\$\$) 2,597.16

Total Parts (\$\$) 28,568.76

Munich Autocare Pte Ltd/SMW1455P/09/01/2023 18:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Repairer Estimates

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BRAKE OIL	18.00
2	10	FENDER INNER SHIELD CLIP	70.00
Sub Total (S\$)			88.00

Estimates on Labour

No Particulars

Labour Items	Lab.Type	Amount
1 TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER, SUPPORT PANEL , FENDER RH, FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH AND DAMAGE AREA	New	1,500.00
2 TO CHECK ALL WIRING FOR OPERATION		
3 TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	120.00
4 TO REFIX AND REPLACE FRONT SIDE MIRROR RH , DOOR LOCK , WINDOW GLASS , REGULATOR WITH MOTOR MECHANISM	New	380.00
5 TO CONDUCT 4 WHEEL ALIGNMENT & BALANCING		
6 TO REMOVE & INSTALL FRONT LH AND REAR LH SUSPENSION AND UNDERCARRIAGE CONTROL SYSTEM AND INCLUDING TO REPLACE DAMAGED PART	New	80.00
7 TO DISMANTLE ROOF LINING AND INSTALL ALL ELECTRICAL COMPARTMENTS , CONTROL UNITS AND SIDE COMPARTMENT TRIM BOARD TO REPLACE RIGHT SIDE CUSHION AIR BAG N SEAT AIR BAG RH	New	350.00
8 TO RESPRAY FRONT FENDER RH ,FRONT DOOR RH , REAR DOOR RH, ROCKER PANEL RH AND DAMAGE AREA	New	1,200.00
Gross Labour Cost (S\$)		4,100.00

Munich Autocare Pte Ltd/SMW1455P/09/01/2023 18:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

055D

SMW1455P

No

05 Jan 2023

RENAULT

SCENIC IV 1.5L DCI AT EU6

Red

2019

K9KF649D059983

VF1RFA00663699345

81.0 kW (108 bhp)

\$23,315.00

04 Nov 2020

04 Nov 2020

0

\$14,641.00

Yes

03 Nov 2030

\$10,980.00

03 Nov 2030

A - Car up to 1600cc & 97kW (130bhp)

10

\$38,504.00

\$30,141.00

\$41,121.00

The information contained herein is correct as at 05 Jan 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/01/2023 15:43 (SGT)
Reported by	Driver
Date of Accident	01/01/2023 23:58 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CHOA CHU KANG WAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMW1455P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Scenic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY


Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2002451400

DRIVER

Name of Driver	KOH CHEE HONG
NRIC No	SXXXX845E
Date Of Birth	16/06/1957
Occupation	Outdoor

SKETCH PLAN

CHOA CHU KANG WAY



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On. 1/1/23 @ 11.58 pm while I driving
along Choa Chu Kang Way and I didn't notice
Traffic light is red which I continued drive
and beat the red light. Vehicle B coming
from my Right and hit my right side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

