

ASS. REC. BY:

REF:

C72 / 230003161Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

8155k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

9

Consistent? : Yes or No

Est. Repairs:

8-7-10 days

Res.: Yes or No

Lum Sum:

1-1-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 182k Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW M240i c.c. 2998

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

68012

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2J52040V072525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

Pir

225 / 40 R18

R:

245 / 35 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

9

mm

L/Bal.

7

mm

L/Bal.

9

mm

D.O.A.

6/1/23

D.O.I.

10/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

4/5

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/3/21 Rev B 14,400k

10/5/21 Rev B 14,600k (Red. \$11930.90, 45%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 11/5/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8 9

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/01/2023 10:43 (SGT)
Reported by	Both
Date of Accident	06/01/2023 19:20 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS CHANGI (AFTER SIMS AVE EXIT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME162K
-----------------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WUN WEN-NA
NRIC No	SXXXX148G
Email Address	WENNA.WUN@GMAIL.COM
Mobile Phone No	(Phone) +65-90703231
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	M240i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2998

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SI22V11148/VPS/R02

DRIVER

Name of Driver	WUN WEN-NA
NRIC No	SXXXX148G
Date Of Birth	23/11/1969
Occupation	Indoor

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

g. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")


(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



Sketch Plan

Vehicle A: SME 162 K

Vehicle B: SJN 8309 R

Vehicle C: SJJ 1502 R

The diagram shows a road with three lanes, represented by vertical lines. Three vehicles are shown in the middle lane, stacked vertically. Each vehicle is represented by a rectangle with a triangle on top. The top vehicle is labeled 'C', the middle one 'A', and the bottom one 'B'. Each vehicle has a small 'X' mark on its front (the side closer to the top of the stack).


Describe Circumstance of the Accident


On the stated date & time, I was travelling along PIE towards Changi after Sims Ave exit. Suddenly vehicle C jammed brake, I managed to stop in time without any collision. Unfortunately after I stopped, vehicle B came and couldn't stop in time and collided to rear portion of my vehicle, caused my vehicle to propel forward and collided to rear portion of vehicle C.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email: chingmotorrepair@gmail.com

7-10 Days

Not Authorised
14,600
11 Day @ 14,400

M/s Ching Teiping Insurance (S) Pte Ltd

DATE

07.01.2023

3 Anson Road #16-00 Spring leaf Tower

CAR NO

SME 162 K

Singapore 079909

MAKE

BMW

9 Days
Mummy After Repair

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED: SJA 8309 R

Pc	Pcs	WBA2J52040VD72525	UNIT PRICE	AMOUNT
1	pc	Rear boot		\$1,281.20
2	pcs	Rear boot hinge (left & right)	\$75.80	\$151.60
1	pc	Rear boot weather strip		\$141.50
1	pc	Rear boot lock		\$205.40
1	pc	Rear boot lock striker		\$67.95
1	pc	Rear boot insulator		\$92.70
1	pc	Rear boot inner top board cover		\$758.55
1	pc	Rear boot top spoiler		\$92.95
1	pc	"BMW" emblem		\$103.80
1	pc	"M240i" emblem		\$1,137.60
2	pcs	Tail lamp (left & right)	\$568.80	\$1,137.60
1	pc	Rear bumper		\$1,141.65
10	pcs	Rear bumper clips	\$3.00	\$30.00
1	pc	Rear bumper sponge		\$168.00
2	pcs	Rear bumper stay (left & right)	\$128.00	\$256.00
2	pcs	Rear bumper side retainer (left & right)	\$155.80	\$311.60
2	pcs	Rear bumper reverse sensor	\$273.95	\$547.90
1	pc	Rear bumper lower lip		\$283.45
1	pc	Rear bumper tow cover		\$55.95
2	pcs	Rear bumper lamp (left & right)	\$49.00	\$98.00
1	pc	Rear bumper inner beam		\$467.85
1	pc	Rear bumper upper guide		\$179.90
1	pc	Rear bumper lower guide		\$199.50
1	pc	Rear end panel		\$552.40
1	pc	Rear end panel top garnish		\$112.50
1	pc	Rear end panel top garnish clips	\$5.00	\$40.00
1	pc	Rear spare tyre tank panel		\$495.50
1	pc	Rear spare tyre panel cover board		\$85.70
1	pc	Rear spare tyre panel heat shield (left & right)	\$82.70	\$165.40
1	pc	Rear number plate with casing		\$95.00
1	pc	Rear exhaust box		\$1,287.80
1	pc	Rear exhaust pipe		\$1,230.50
1	pc	Keyless sensor		\$168.00
1	pc	Keyless kick module		\$595.00

shorted

bent

Page 1 of 3 Total

San Lim

Ching Motor Repair Shop.

11610-45

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

M/s China Taiping Insurance (S) Pte Ltd

DATE 07.01.2023

3 Anson Road #16-00 Spring leaf Tower

CAR NO SME 162 K

Singapore 079909

MAKE B M W

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SJN 8309 R

Pc	Pcs	WBA2J52040VD72525	UNIT PRICE	AMOUN*
		Continue from page one.		
1	pc	Front bumper		B 12,604.85
1	pc	Front bumper sponge		B 1,274.35
1	pc	Front bumper reinforcement		B 97.45
2	pcs	Front bumper bracket (LH & RH)		B 423.70
2	pcs	Front bumper side retainer (LH & RH)		B 247.60
2	pcs	Front bumper centre chrome grille		B 133.10
1	pc	Front bumper tow cover		B 132.50
1	pc	Front bumper "BMW" logo		B 55.70
2	pcs	Front bumper sensor		B 82.85
1	pc	Front number plate with casing		B 551.90
2	pcs	Front head lamp (LH & RH) mtg cra		B 95.00
				B 2,260.55
				B 4521.90

Page 2 of 3 Total

San Lim

Ching Motor Repair Shop.

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

N/A	China Taiping Insurance (S) Pte Ltd	DATE	07.01.2023
	3 Anson Road #16-00 Spring leaf Tower	CAR NO	SME 162 K
	Singapore 079909	MAKE	B M W

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
INSURED : SJN 8309 R

Pos	WBA2J52040VD72525	UNIT PRICE	AMOUNT
Continue from page two.			\$20,220.90
Straightening and panel beating on all accident affected parts, jacking front bonnet, jacking rear two side fender, cutting rear end panel, rear spare tyre tank panel, dismantle & replace the above front and rear mentioned parts.		\$2,500.00	1000/
Labour for respray front bonnet, front bumper, rear end panel, rear bumper, rear spare tyre tank panel, rear boot lid, rear left & right side fender.		\$2,400.00	1250/
Computer coding of front two head lamp, electrical wiring including & focusing adjustment.		\$300.00	3d
Scanning and diagnose of computer for front two side head lamp.		\$250.00	12d
Program and reset the whole electrical & electronic system.		~ \$500.00	X
To perform water leakage test.		\$80.00	30/
To testing and replace front & rear reverse sensor.		\$80.00	/
Labour for dismantle & replace rear exhaust.		\$200.00	80/