

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG 23000323/493

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

20/1/23 2/3 @ 6500 informed Vincent

SOON SAN MOTOR TRADING

Elk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG Building

S,pore 079120

Accident date:09/01/2023

Date:10/01/2023

SLJ

Estimate cost to repair vel: SLJ 2959B (Toyota Wish) claims under vel: GBD4844K.

not allowed
her
10/1/23
1/5 * 6500
6 days

1pce tailgate	\$ 1,599.30	Body as -
1pce tail gate emblem	67.70	ner -
2pcs tail gate windscreen side <u>rubber@\$37.80</u>	75.60	ner -
1pce tail gate windscreen inner sealant	140.00	ner 40 S/N
1set tail gate windscreen tape from	65.20	ner 30 S/N
1pce tail gate valve matic plate	44.40	ner 40 S/N
1pce tail gate rubber	363.60	twi -
2pcs tail gate damper@\$216	432.00	u7 X
2pcs tail gate <u>reflector@\$318.20</u>	636.40	cre -
1pce tail gate top lock	446.30	twi -
1pce tail gate lower lock catch	44.30	u7 X
1pce tail centre lock switch	193.90	cre -
1pce tail gate centre chrome	368.00	cre -
1pce tail gate trim cover garnish	393.20	Re/Torn -
2pcs rear fender side trim cover@\$402	804.00	Re/Torn -
1pce tail gate wiper motor	398.20	Ref/Torn -
2pcs tai <u>lamp@\$383.60</u>	767.20	u7 X
2pcs tail lamp inner panel@\$215	430.00	R X
1pce rear panel	580.80	Body as -
1pce rear panel lower lock catch cover	198.50	twi -
1pce rear bumper	693.70	Dis -
1set rear bumper reverse sensors	350.00	Shad 200 S/N
2pcs rear bumper inner <u>bracket@\$68.30</u>	136.60	u7 X
2pcs rear bumper top side clip@\$12	24.00	u7 X
1set 10pcs rear bumper inner clip@\$8	50.00	ner -
2pcs rear bumper side <u>holder@4105.50</u>	211.00	Ref -

1set

1pce rear Exhaust pipe
2pcs rear Fenders \$1,158.50

\$1,295.40
\$2,317.00

page 1

Ref -

R X

R X

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG Building

S,pore 079120

Accident date:09/01/2023

Date:10/01/2023

Estimate cost to repair vel: SLJ 2959B (Toyota Wish) claims under vel: GBD4844K.

2pcs rear bumper side	\$ 99.40
2pcs rear bumper inner lower bracket@ \$15	30.00
1pce rear spare panel	980.00
	\$11,094.00
Less 20%	2,218.80
	\$8,875.52
1pce rear number plate with cover	100.00
To rustproof	200.00
To remove/refit rear windscreen	140.00
To remove/refit rear interior to effect repair	100.00
To dismantle/renew tail gate	150.00
To check wiring	50.00
To dismantle/renew reverse sensors	80.00
To remove/refit top spoiler	100.00
To dismantle/renew accident portion	1,500.00
To spray paint	1,500.00
Total:	\$12,745.52
LPK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey	

LPK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
--	--

Acknowledged by Repairer

Signature:

Date:

P-7179.60

$$\begin{array}{r} 252 \\ 7-5384.70 \\ \text{S.N}-350 \\ L-2490 \\ \hline 8224 \end{array}$$