


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA YARIS CROSS
 Engine/Chassis No.: MXPB103000610
 Date of accident: 09.01.23
 Damaged area: N/S

Date: 10/01/2023
 Claim Type: TP
 VRN: SMY8601C



Not Notified
 11 Lp & 8000/r
 Memory After Paint
 6 days

List Items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Front fender n/s <i>580.30</i> <i>RT</i>	1	\$ 1,129.00	\$ 1,129.00	✓
2	Front fender inner shield n/s <i>190.20</i> <i>CMT</i>	1	\$ 285.00	\$ 285.00	✓
3	Headlamp n/s <i>1855.30</i> <i>MYCMT</i>	1	\$ 2,365.00	\$ 2,365.00	✓
4	Headlamp lower bracket n/s <i>CMT</i>	1	\$ 109.00	\$ 109.00	✓
5	Front bumper <i>980.20</i> <i>RT/CMT</i>	1	\$ 1,069.00	\$ 1,069.00	✓
6	Front bumper lower moulding <i>CMT</i>	1	\$ 396.00	\$ 396.00	✓
7	Front bumper side retainer <i>RT</i>	2	\$ 114.00	\$ 228.00	✓
8	Front bumper side lamp n/s <i>CMT</i>	1	\$ 487.00	\$ 487.00	✓
9	Front bumper foglamp inner bracket n/s <i>RT</i>	1	\$ 166.00	\$ 166.00	X
10	Front bumper lower grille <i>RT</i>	1	\$ 565.00	\$ 565.00	X
11	Radiator grille bracket <i>RT</i>	1	\$ 147.00	\$ 147.00	X
12	Front shock absorber n/s <i>606</i> <i>RT</i>	1	\$ 689.00	\$ 689.00	✓
13	Front shock absorber mounting n/s <i>RT</i>	1	\$ 195.00	\$ 195.00	X
14	Front lower arm n/s <i>RT</i>	1	\$ 487.00	\$ 487.00	✓
15	Front wheel knuckle n/s <i>3 458</i> <i>RT</i>	1	\$ 598.00	\$ 598.00	✓
16	Front wheel bearing n/s <i>RT</i>	1	\$ 290.00	\$ 290.00	✓
17	Front end link n/s <i>RT</i>	1	\$ 214.00	\$ 214.00	✓
18	Headlamp top support n/s <i>RT</i>	1	\$ 215.00	\$ 215.00	X
19	Front bumper reinforcement <i>RT</i>	1	\$ 677.00	\$ 677.00	X
20	Front bumper impact absorber <i>CMT</i>	1	\$ 189.00	\$ 189.00	✓
21	Front fender inner top bracket n/s <i>RT</i>	1	\$ 159.00	\$ 159.00	X
22	Front door n/s <i>RT</i>	1	\$ 1,453.00	\$ 1,453.00	X
23	Front door hinge n/s <i>RT</i>	2	\$ 98.00	\$ 196.00	X
24	Front door checker n/s <i>RT</i>	1	\$ 75.00	\$ 75.00	X
25	Wing mirror assy n/s <i>812</i> <i>RT/CMT</i>	1	\$ 913.00	\$ 913.00	✓
26	Bonnet <i>RT</i>	1	\$ 1,219.00	\$ 1,219.00	X
27	Bonnet hinge <i>RT</i>	2	\$ 132.00	\$ 264.00	X
28	Wiper washer tank <i>RT</i>	1	\$ 267.00	\$ 267.00	X
29	Wiper washer tank motor <i>RT</i>	1	\$ 313.00	\$ 313.00	X
30	Front fender arch garnish n/s <i>MY</i>	1	\$ 215.00	\$ 215.00	✓
31	Front bumper lower deflector <i>RT</i>	1	\$ 169.00	\$ 169.00	X

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2591
 267

Repair Estimate

32	Front bumper lower grille side cover n/s	Sh	1	\$ 89.00	\$ 89.00	X
33	Front door lower moulding n/s	Sh	1	\$ 195.00	\$ 195.00	X
34	Front fender inner panel n/s	Sh	1	\$ 553.00	\$ 553.00	X
35	Front fender inner support bracket n/s	Sh	1	\$ 129.00	\$ 129.00	X
36	Front wheel ABS sensor n/s	Sh	1	\$ 148.00	\$ 148.00	✓
37	Rocker panel outer moulding n/s	CM	1	\$ 337.00	\$ 337.00	✓
38	Front cross member	Sh	1	\$ 1,853.00	\$ 1,853.00	✓
39	Front bumper inner sponge	Sh	1	\$ 184.00	\$ 184.00	X
				Subtotal	\$ 19,231.00	
				List discount	25.00%	
				Total	\$ 14,423.25	

Special nett items					
No.	Parts description		QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	me	12	\$ 5.50	\$ 66.00
2	Front fender inner shield clips n/s	han	8	\$ 5.50	\$ 44.00
3	Front door inner trim board clips n/s	nn	12	\$ 5.50	\$ 66.00
4	Bonnet insulator clips	nn	12	\$ 5.50	\$ 66.00
5	Front tyre n/s	Per	1	\$ 380.00	\$ 380.00
6	Front alloy rim n/s	nd	1	\$ 550.00	\$ 550.00
7	Front fender arch garnish clips n/s	nn	8	\$ 5.50	\$ 44.00
8	Sundries	nn	1	\$ 50.00	\$ 50.00
Total					\$ 1,266.00

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	600l
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00	20l
3	To remove and refit n/s front tyre & rims. To perform tyre balancing.	0.25	\$ 50.00	20l
4	To remove and refit n/s front undercarriage for replacement of parts.	1	\$ 200.00	✓
5	To conduct computerized wheel alignment.	0.5	\$ 100.00	60l
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00	720l
7	To rust proof all affected portions after repair.	0.5	\$ 100.00	30l
			Total labour	\$ 3,100.00

Estimate Grand Total	\$ 18,789.25
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged parts during respray
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and
- is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date: