

Date: 06/01/2023

Vehicle No: SMY3745D

Model: TOYOTA PRIUS 5DR HATCHBACK

Chassis: JTDKB3FU503091585-2020

Reg.Year: 2021

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SLB1081G

Date of Accident: 05/01/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Per</i> \$458.00
2	REAR BUMPER REINFORCEMENT	1		\$336.00
3	REAR BUMPER LOWER LIP	1		<i>Not</i> \$486.00
4	REAR TAILGATE	1		REPAIR
SUB TOTAL				\$1,280.00
LESS 25%				-\$320.00
PARTS TOTAL				\$960.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Per</i> \$50.00
2	REAR BUMPER REVERSE SENSOR	1		\$300.00
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

200
\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER & ETC.

200
\$500.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *50*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

un \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

un \$100.00 X

LABOUR TOTAL \$1,340.00

TING AN

TOTAL \$2,650.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

