

Invoice Name & Address

CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



ESTIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Owner Name & Vehicle Info

VOIL VOICE HYNG CAROLVII		Cust No/Name	/K	OH YOKE MING	CAROLY	N			
	KOH YOKE MING CAROLYN		Reg No/Reg Date	SNJ623J	/ 20/12/20	22			
78 CHARTWELL DR		Date In/Mileage		/ 0					
	SERANGOON GARDEN ESTATE			Chassis No	VR7BAHNSBN				
	SINGAPORE 558773		Engine No						
					10XVDW1902				
	Contact No	Mobile: 96622654		Make/Model		L 1.2 PURETE			
				Colour/Trim	9VM NOIR P	ERLA NERA/ S	OF URBA	N GREY F	ABR
ccount No	Terms	Date/Time Printed	CSE	Operator		WIP No			
SM00073	Cash	07/01/2023/ 13:55		1015/ Vikneswaran	Naidu A	19600			
		Description of Goo	ods / Services		Qty	Unit Price	Disc%	An	nount
PNT98000 SPRAY F DOOR TR	M PANEL, RE	OR, REAR RH DOOR, REPAIR ROCKER PANEL R OR, REAR RH DOOR, RH	H 🗙					1100	3300.0
10028901 TO CARR	Y OUT DIAGN	OSTIC CHECK ON ELEC	TPONIC CONTRO	N CVCTEM					380.0
10028901	. oo. binan	iosite eneck on elec	INDITE CONTRO	IL STSTEM				100	158.0
CHECK EI	LECTRICAL A	ND WIRING						100	1,0.0
PNT88000	LECTRICAL A	10 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m						100	
PNT88000 REMOVE	a harmonia de la granda de la gr	ND WIRING							
PNT88000 REMOVE A PNT88000	AND REFIT D	OOR TRIM RH FRONT							180.0
PNT88000 REMOVE / PNT88000 REMOVE /	AND REFIT D	OOR TRIM RH FRONT	D PANEL			· · · · · · · · · · · · · · · · · · ·			180.0
PNT88000 REMOVE / PNT88000 REMOVE / SUNDRY	AND REFIT D	OOR TRIM RH FRONT	D PANE		te	*			180.0
PNT88000 REMOVE / PNT88000 REMOVE /	AND REFIT D	OOR TRIM RH FRONT	D PANEL					(57	180.0
PNT88000 REMOVE / PNT88000 REMOVE / SUNDRY SUPPLY S	AND REFIT D	OOR TRIM RH FRONT	D PANEL		ie			(57	180.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY	AND REFIT D AND REFIT R SEALANT LM TINT RH	OOR TRIM RH FRONT EAR RH DOOR TRIM AN	D PANE					(57	180.0 160.0 128.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS	AND REFIT D AND REFIT R SEALANT	OOR TRIM RH FRONT EAR RH DOOR TRIM AN	D PANEL					(57	180.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS SUNDRY	AND REFIT D AND REFIT R SEALANT LM TINT RH ST PROOFING	OOR TRIM RH FRONT EAR RH DOOR TRIM AN	D PANE					(57	180.0 160.0 128.0
PNT88000 REMOVE // PNT88000 REMOVE // SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS SUNDRY SUNDRY SUNDRY SUNDRY	AND REFIT D AND REFIT R SEALANT LM TINT RH ST PROOFING	OOR TRIM RH FRONT EAR RH DOOR TRIM AN	D PANE					20 100 100	180.0 160.0 120.0 280.0 200.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS SUNDRY ANTI RUS SUNDRY SUNDRY SUNDRY SUNDRY SUNDRY SUNDRY SUNDRY ANTI RUS SUNDRY SUNDR	AND REFIT D AND REFIT R SEALANT LM TINT RH ST PROOFING	OOR TRIM RH FRONT EAR RH DOOR TRIM AN	D PANE					(57	180.0 160.0 128.0
PNT88000 REMOVE / PNT88000 REMOVE / SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS SUNDRY SUNDRY SUNDRY CALIBRAT	AND REFIT D AND REFIT R SEALANT LM TINT RH ST PROOFING	FRONT	D PANE					20 100 100	180.0 160.0 120.0 280.0 200.0
PNT88000 REMOVE / PNT88000 REMOVE / SUNDRY SUPPLY S SUNDRY SOLAR FI SUNDRY ANTI RUS SUNDRY SUNDRY SUNDRY CALIBRAT	AND REFIT D AND REFIT R SEALANT LM TINT RH ST PROOFING	FRONT	D PANE		1.00	1210.00	0.00	20 100 100	180.0 160.0 120.0 280.0 200.0 80.0 380.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANTI RUS SUNDRY SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN	AND REFIT D AND REFIT R GEALANT LM TINT RH GT PROOFING TON ON POWE	FRONT X ER WINDOW INCLUDING	D PANE		1.00	127.00	0.00	20 100 100	180.0 160.0 280.0 290.0 80.0 380.0 1210.0 127.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR HIN	AND REFIT R SEALANT LM TINT RH ST PROOFING TON ON POWE OR RH A 54 GE RH SUP	EAR RH DOOR TRIM AN FRONT ** ER WINDOW INCLUDING ** ** ** ** ** ** ** ** **	D PANE		1.00	127.00 127.00	0.00	20 100 100	180.0 160.0 120.0 280.0 290.0 80.0 1210.0 127.0 127.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR CHE SEALING	AND REFIT D AND REFIT R SEALANT LM TINT RH T PROOFING TON ON POWE OR RH A 54 GE RH SUP GE RH SUP GE RH INE CKSTRAP PANEL R	EAR RH DOOR TRIM AN FRONT X ER WINDOW INCLUDING	D PANE		1.00 1.00 1.00	127.00 127.00 100.00	0.00 0.00 0.00	20 100 100	180.0 160.0 120.0 280.0 290.0 80.0 1210.0 127.0 100.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR CHE SEALING	AND REFIT D AND REFIT R SEALANT LM TINT RH T PROOFING TON ON POWE OR RH A 54 GE RH SUP GE RH SUP GE RH INE CKSTRAP PANEL R	EAR RH DOOR TRIM AN FRONT X ER WINDOW INCLUDING	D PANE		1.00 1.00 1.00 1.00	127.00 127.00 100.00 94.00	0.00 0.00 0.00 0.00	20 100 100	180.0 160.0 280.0 290.0 380.0 1210.0 127.0 100.0 94.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR CHE SEALING DR WEATH MOULDING	AND REFIT D AND REFIT R SEALANT LM TINT RH IT PROOFING TON ON POWE OR RH A bill GE RH SUP GE RH SUP GE RH INE CKSTRAP PANEL R ERSTRIP RH	EAR RH DOOR TRIM AN FRONT X ER WINDOW INCLUDING	D PANE		1.00 1.00 1.00 1.00	127.00 127.00 100.00 94.00 190.00	0.00 0.00 0.00 0.00	20 100 100	180.0 160.0 280.0 200.0 380.0 1210.0 127.0 100.0 94.0 190.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR CHE SEALING DR WEATH MOULDING PROTECTE	AND REFIT D AND REFIT R SEALANT LM TINT RH T PROOFING TON ON POWE OR RH A 51 GE RH SUP GE RH SUP GE RH INE CKSTRAP PANEL R ERSTRIP UR 500	FRONT X ER WINDOW INCLUDING	D PANE		1.00 1.00 1.00 1.00 1.00	127.00 127.00 100.00 94.00 190.00 138.00	0.00 0.00 0.00 0.00 0.00	20 100 100	180.0 160.0 120.0 280.0 290.0 80.0 1210.0 127.0 100.0 94.0 190.0 138.0
PNT88000 REMOVE A PNT88000 REMOVE A SUNDRY SUPPLY S SUNDRY SOLAR F1 SUNDRY ANT1 RUS SUNDRY SUNDRY CALIBRAT FRONT DO DOOR HIN DOOR CHE SEALING DR WEATH MOULDING PROTECTE	AND REFIT D AND REFIT R SEALANT LM TINT RH IT PROOFING TON ON POWE OR RH A bill GE RH SUP GE RH SUP GE RH INE CKSTRAP PANEL R ERSTRIP RH	FRONT X ER WINDOW INCLUDING	D PANE		1.00 1.00 1.00 1.00	127.00 127.00 100.00 94.00 190.00	0.00 0.00 0.00 0.00	20 100 100	180.0 160.0 280.0 200.0 80.0 1210.0 127.0 100.0 94.0 190.0

Authorized signatory and company stamp

(a) idity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

istimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would adult and needed for repairs or replacement. we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also among a first and the count of instruments breakens in the count of payable before commencement of the work. cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



ESTIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info					
ALDAL W	Cust No/Name	/KOH YOKE MING CAROLYN					
KOH YOKE MING CAROLYN	Reg No/Reg Date	SNJ623J / 20/12/2022					
78 CHARTWELL DR	Date In/Mileage	/ 0					
SERANGOON GARDEN ESTATE SINGAPORE 558773	Chassis No	VR7BAHNSBNE025145					
STHORPORE SSOTTS	Engine No	10XVDW1902257					
Contact No Mobile: 96622654	Make/Model	CIT/C4 FEEL 1.2 PURETECH 130					
20 mm	Colour/Trim	9VM NOIR PERLA NERA/ SOF URBAN GREY FABR					

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00073	Cash	07/01/2023/ 13:55		1015/ Vikneswaran Nai	du A	19600		
		Description of Goo	ds / Services		Qty	Unit Price	Disc%	Amount
M DOOR HING	E RH SUP	VNA			1.00	70.00	0.00	70.00
M DOOR HING		XMM			1.00	127.00	0.00	127.00
M PLUG NA	age to see that the first				8.00	11.00	0.00	88.00
		M 20 AL			4.00	12.00	0.00	48.00
M FRT DOOR		MA			1.00	232.00	0.00	232.00
M WINDOW LI	FTER RH	X NH			1.00	456.00	0.00	456.00
M SIDE SILL	SEAL X	NH			1.00	127.00	0.00	127.00
N SIDE SILE	JEAL /	49			1.00	127.00	0.00	127

- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final appropriate.

Confirm & accepted by		
этим и иссертен ру	Parts	4,754.00
	Labour	10,630.00
	Standard Menu	0.00
And the second s	Specialist Job	0.00
Authorized signatory and company stamp	Diagnostics Job	0.00
	Sundry/Others	680.00
alidity of this estimate is 14 days from date of quote. This is	Total (w/o GST)	16,064.00

nis estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after a standard and required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you place be interested and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to the second or other repair requiring cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



Exceptional Journeys

INSURANCE CO.: CHINA TAIPING

Supplementary Parts For Registration No.:

SNJ 623 J

	<u>Parts</u>		Cost (\$)
1	Manuf label M		2.00
2	Protecteur Sol		327.00
		La Si vice i	
		Total Parts	329.00
	<u>Labour</u>		Cost (\$)
1	Repair RH side rocker panel		720.00 /
2	Respray Rh side Rocker panel		550.00
		Total Labour	1,270.00
	And the second s	Taxable amount	 1,599.00
	(Note of the Control	8% GST	127.92
		Grand total	\$ 1,726.92

Thank You.

Yours faithfully

LOI AI TING

Senior Officer - Admin

CITROEN SERVICE CENTRE

DID: 6568 4556 / 6568 4501 FAX: 6567 5258 / 6565 1240