

ASS. REC. BY:

REF:

C72/23 000335/K9p3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

NGS

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 15 + B.T. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Sink 72474 Yr Regn: 04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pinta G c.c. 1496

Colour

M. Silver A/C: Insured / Std / NI / NA

Sp. Reading

201156 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MITF 28143 X 00063304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Aviro

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 1/1/23

D.O.I. 10/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1/23 21:00 @ 5900 Cash (Red, \$4804.17, 45%)

Date/Time, File Pass to?

☐

Prell. Report

1) 18/1/23

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

5900

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 e-mail : ngs motorsport pte ltd@gmail.com

Reg No: 201812604N

09/01/2023

China TaiPing Insurance (S) Pte Ltd
Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 01/01/2023@20:10HRS
VEH NO.: SMK7247Y & PC6610U
CLAIMS AGAINST PC6610U
VEH NO.: SMK7247Y (IN WORKSHOP)

We submit herewith our direct third party claim estimate quotation as follow:-
Replacement parts:

1	Back Door	1121.80	Rh	\$	1,185.00	✓
1	Garnish, Back Door (Chrome)		way/cor	\$	211.58	✓
1	Stopper, Back Door Lwr			\$	49.81	X
2	Stopper, Back Door Lwr RH/LH		Rh	\$	99.62	X
1	Lock, Back Door, W/Courtesy Lamp Switch		Trm	\$	359.32	✓
1	Striker Assy, Back Door			\$	48.62	X
2	Stay/Damper, Back door Upp RH/LH		Rh	\$	509.22	X
1	Glass, Back Door		shorten	\$	1,324.84	✓
1	Weatherstrip, Back Door		Dis/In	\$	219.98	✓
1	Moulding, Back Door, outside		rh	\$	38.87	✓
2	Moulding, Back Door, outside RH/LH		rh	\$	77.74	✓
1	Board Assy, Back Door Trim		Bu	\$	189.57	✓
2	Taillamp RH/LH	N/S Ro		\$	707.72	✓
2	Boot Lamp RH/LH	N/S Ro		\$	469.52	✓
1	Lamp Set, Stop Center		rh	\$	189.42	X
2	License Lamp RH/LH		cm	\$	178.84	✓
1	Rr Wiper Motor		\$rh	\$	388.39	X
1	Rr Wiper Arm		rh	\$	73.96	X
1	Rr Wiper Blade		rh	\$	65.80	X
1	Rear Bumper	342	Bu/rh	\$	399.68	✓
2	Extension, Rear Bumper RH/LH		\$115.69	\$rh	231.38	X
1	Extension, Rear Bumper Ctr		nd/ly	\$	188.13	✓
1	Plate, Rear Bumper LH		\$rh	\$	20.00	X
2	Seal, Rear Bumper RH/LH		Dis	\$	98.28	✓
2	Support Rear Bumper RH/LH		Dis	\$	158.44	✓
1	Retainer, Outside RH/LH		N/S Dis	\$	162.78	✓
2	Side Retainer RH/LH		N/S Dis	\$	190.00	✓
1	Panel, Lower Back Outer		Rh	\$	394.42	✓

NOT ADVISED
Penny B4ping
6 days
11/Jan @ 590dp

Vehicle SMK7247Y

1	End Panel Lower Back	608-10		\$ 632.88	✓
1	Cover, Slide door ctr Rail LH	522-10		588.62	✓
				\$ 9,452.43	
			Less 25%	\$ (2,363.11)	
				\$ 7,089.32	
4	Cushion/Clips, Rear Bumper	S.Nett	NA \$ 36.88	\$ 147.52	60sn
1	Badge, Back Door	S.Nett	NA \$	52.40	—
1	Back Door Name 'SIENTA'	S.Nett	NA \$	52.40	—
1	Back Door Name 'G'	S.Nett	NA \$	42.53	—
1	No Plate c/w casing	S.Nett	NA \$	50.00	45sn
1	Sealant	S.Nett	NA \$	60.00	40sn
1	Parking Sensor	S.Nett	NA \$	280.00	X

To remove all damaged part with all necessary components/attachments. \$ 1,600.00 700l
 Straighten chassis member, repair/reshape dented body panel in accordance with factory specifications. Replace/reposition damaged parts, refit align into position. Refix all necessary components/attachments.

To transfer back door & all mechanism & ect \$ 100.00 60l

To replace rear windscreen glass \$ 180.00 120l

Spray paint on replace/repair body parts. \$ 1,000.00 700l

To remove/refit wire harness, all related connector, check proper function. \$ 50.00 20l
\$ 10,704.17

Any other parts which necessitate repair or renewal will incur additional charged.
 Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	601D
Vehicle Details	
Vehicle No.:	SMK7247Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA STANDARD (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	2NRX444968
Chassis No.:	MHFZ28H3X00063304
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$17,365.00
Original Registration Date:	23 Apr 2019
First Registration Date:	23 Apr 2019
Transfer Count:	1
Actual ARF Paid:	\$17,365.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2029
PARF Rebate Amount:	\$13,023.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$18,321.00
Total Rebate Amount:	\$31,344.00

The information contained herein is correct as at 09 Jan 2023

OK