

ASS. REC. BY: Taufik

REF: α/11822002246/1993

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. 2022 22004141SL
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: A125K.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMN 3185C Yr Regn: 2019 / July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Hammer c.c. 1998
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 128882 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STE 21364 X 05004626
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 235/55R18
R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 10/3/27 @ 12pm
Survey held at Galaxy Auto.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$4700, 4 days. (Red \$13401.30, 74%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) 15/06 Typist

Date/Time, File Return to?

2) _____

Rep. Format: TP

Lump Sum 4700

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

GALAXY AUTO CARE PTE LTD

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-23 Singapore 417807

Tel: 9090 8488 / Email: galaxyautosg@gmail.com

VEHICLE NO: SMN3185C

MAKE & MODEL: TOYOTA HARRIER

DOA: 6/3/2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 2,659.50	bt✓
TAILGATE INNER TRIM BOARD	1	\$ 668.70	X
TAILGATE WEATHERSTRIP	1	\$ 420.66	twi✓
TAILGATE INNERLOCK	1	\$ 763.45	bt✓
TAILGATE ELECTRONIC DAMPER @ SGD390.52	2	\$ 781.04	X
TAILGATE WINDSCREEN MOULDING	1	\$ 271.64	nel✓
TAILGATE LOGO	1	\$ 101.40	nel✓
TAILGATE EMBLEM 'HARRIER'	1	\$ 95.80	nel✓
TAILGATE EMBLEM 'TUBRO'	1	\$ 95.80	nel✓
TAILGATE SIDE RUBBER @ SGD98.20	1	\$ 196.40	Xnn
TAILGATE OUTER GARNISH	1	\$ 490.50	Xnn
TAILGATE OUTER OPENING SWITCH	1	\$ 295.65	Xnn
TAILGATE REFLECTOR LAMP @ SGD714.20	2	\$ 1,428.40	Xnn
TAIL LAMP ASSY @ SGD1108.52	2	\$ 2,217.00	Xnn.
REAR BUMPER	1	\$ 1,852.20	de✓
REAR BUMPER DIFFUSER	1	\$ 720.65	de✓
REAR BUMPER SIDE RETAINER @ SGD120.20	2	\$ 240.40	Xnn
REAR BUMPER BRACKET @ SGD78.20	2	\$ 156.40	Xnn
REAR BUMPER SPONGE	1	\$ 196.70	cn✓
REAR BUMPER TOW COVER	1	\$ 48.20	Xnn
REAR BUMPER DISTANCE SENSOR @ SGD289.40	2	\$ 1,157.60	nn✓ 578.80
REAR BUMPER SENSOR BRACKET	1	\$ 178.50	nel✓
REAR BUMPER CENTRE UNDER GARNISH	1	\$ 296.40	Xnn.
REAR END REINFORCEMENT ADJUSTER	1	\$ 695.40	bt✓
REAR END REINFORCEMENT BRACKET	1	\$ 215.42	Xnn
REAR END PANEL	1	\$ 981.65	Ry
REAR END PANEL TOP GARNISH	1	\$ 421.60	de✓

\$ 17,647.06

LESS 25%

\$ 4,411.77

SUB TOTAL

\$ 13,235.30

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR TAILGATE INNER GLASS INNER SEAL/SPONGE TAP	1	\$ 171.00	Xnn.
REAR TAILGATE GLASS SEALANT	1	\$ 100.00	nel✓
REAR END PANEL SEALANT/JOINT	1	\$ 100.00	Xnn
REAR SPARE TYRE PANEL SEALANT/JOINT	1	\$ 100.00	Xnn
REAR NUMBER PLATE	1	\$ 65.00	Xnn.

SUB TOTAL

\$ 536.00

LABOUR	QTY	PRICE (\$)	REMARKS
TO REMOVE, REPAIR & RENEW AFFECTED ACCIDENT AREAS (@SGD 300.00 PER DAY)	1	\$ 1,600.00	600
TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS (@SGD 300.00 PER PANEL)	1	\$ 1,400.00	700.
TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	1	\$ 50.00	30
TO TRANSFER TAILGATE ATTACHMENT, TRIMS, GARNISH TO	1	\$ 150.00	60
TO REMOVE & INSTALL REAR TAILGATE GLASS TO FACILITATE	1	\$ 150.00	120
TO CONDUCT WATER SEAPAGE TEST	1	\$ 150.00	30
TO TRANSFER REAR COMPARTMENT TRIMS, GARNISH TO	1	\$ 150.00	60
TO RE-PROGRAMME & CALIBRATION ECU, SENSOR AFTER REPAIRS	1	\$ 480.00	Xnn.
TO RUST PROOF AFFECTED AREAS	1	\$ 200.00	30

SUB TOTAL \$ 4,330.00

GRAND TOTAL \$ 18,101.30

Taufhin 9744544
 - WP' 10/3/22 @ 120 pm.
 215 Resurvey after repair
 Taufhin @ 11hants w/m
 04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: