

GALAXY AUTO CARE PTE LTD

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-23 Singapore 417807

Tel: 9090 8488 / Email: galaxyautosg@gmail.com

VEHICLE NO: SMN3185C

MAKE & MODEL: TOYOTA HARRIER

DOA: 6/3/2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 2,659.50	bt✓ 1850
TAILGATE INNER TRIM BOARD	1	\$ 668.70	xnn
TAILGATE WEATHERSTRIP	1	\$ 420.66	wt✓ 320
TAILGATE INNERLOCK	1	\$ 763.45	bt✓ 463
TAILGATE ELECTRONIC DAMPER @ SGD390.52	2	\$ 781.04	x
TAILGATE WINDSCREEN MOULDING	1	\$ 271.64	nel✓
TAILGATE LOGO	1	\$ 101.40	nel✓
TAILGATE EMBLEM 'HARRIER'	1	\$ 95.80	nel✓
TAILGATE EMBLEM 'TUBRO'	1	\$ 95.80	nel✓
TAILGATE SIDE RUBBER @ SGD98.20	1	\$ 196.40	xnn
TAILGATE OUTER GARNISH	1	\$ 490.50	xnn
TAILGATE OUTER OPENING SWITCH	1	\$ 295.65	xnn
TAILGATE REFLECTOR LAMP @ SGD714.20	2	\$ 1,428.40	xnn
TAIL LAMP ASSY @ SGD1108.52	2	\$ 2,217.00	xnn.
REAR BUMPER	1	\$ 1,852.20	de✓ 881.10
REAR BUMPER DIFFUSER	1	\$ 720.65	de✓ 466.80.
REAR BUMPER SIDE RETAINER @ SGD120.20	2	\$ 240.40	xnn
REAR BUMPER BRACKET @ SGD78.20	2	\$ 156.40	xnn
REAR BUMPER SPONGE	1	\$ 196.70	cng✓
REAR BUMPER TOW COVER	1	\$ 48.20	xnn
REAR BUMPER DISTANCE SENSOR @ SGD289.40	2	\$ 1,157.60	nw✓ 235
REAR BUMPER SENSOR BRACKET	1	\$ 178.50	nel✓ 55
REAR BUMPER CENTRE UNDER GARNISH	1	\$ 296.40	xnn.
REAR END REINFORCEMENT ADJUSTER	1	\$ 695.40	bt✓ 531
REAR END REINFORCEMENT BRACKET	1	\$ 215.42	xnn
REAR END PANEL	1	\$ 981.65	RY
REAR END PANEL TOP GARNISH	1	\$ 421.60	de✓ 377.80

\$ 17,647.06

LESS 25% \$ 4,411.77

SUB TOTAL \$ 13,235.30

5941.04

4455.78

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR TAILGATE INNER GLASS INNER SEAL/SPONGE TAP	1	\$ 171.00	xnn.
REAR TAILGATE GLASS SEALANT	1	\$ 100.00	nel✓ 60
REAR END PANEL SEALANT/JOINT	1	\$ 100.00	xnn
REAR SPARE TYRE PANEL SEALANT/JOINT	1	\$ 100.00	xnn
REAR NUMBER PLATE	1	\$ 65.00	xnn.
SUB TOTAL		\$ 536.00	60

LABOUR	QTY	PRICE (\$)	REMARKS
TO REMOVE, REPAIR & RENEW AFFECTED ACCIDENT AREAS (@SGD 300.00 PER DAY)	1	\$ 1,600.00	600
TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS (@SGD 300.00 PER PANEL)	1	\$ 1,400.00	700.
TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	1	\$ 50.00	30
TO TRANSFER TAILGATE ATTACHMENT, TRIMS, GARNISH TO	1	\$ 150.00	60
TO REMOVE & INSTALL REAR TAILGATE GLASS TO FACILITATE	1	\$ 150.00	120
TO CONDUCT WATER SEAPAGE TEST	1	\$ 150.00	30
TO TRANSFER REAR COMPARTMENT TRIMS, GARNISH TO	1	\$ 150.00	60
TO RE-PROGRAMME & CALIBRATION ECU, SENSOR AFTER REPAIRS	1	\$ 480.00	Xmm.
TO RUST PROOF AFFECTED AREAS	1	\$ 200.00	30

SUB TOTAL \$ 4,330.00

1630

GRAND TOTAL \$ 18,101.30

Taufhin 97445749

WP 10/3/22 @ 120 pm.

1/2 Resurvey after repair

Taufhin @ 11hanta.com
04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4455.78

60

1630

6145.78

445 4700

04 days