

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG23000342/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

L7A 29578

Date / Time

Action / Instruction

207 11k.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

\$ + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Veh No:

SL E6 P94D

Yr Regn:

29/07/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

K.A

forte k3 c.c 159 /

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

94975

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAF2411M.H 5649048

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45 R17

R:

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

04/01/23

D.O.I.

10/1/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

19/1/23 4/5 & 1300 inbound E/in

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16 January 2023

Not Allowed
here
10/1/23
2/5 & 1300/
2 days

REG NO.: SLE 6894 D
MAKE/MODEL: KIA CERATO K3

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear taillamp -LH	\$ 487.60 X
1	Rear bumper	\$ 688 858.00
1	Rear bumper inner sponge	\$ 145.50 X
1	Rear bumper reflector	\$ 52 95.00
1	Rear bumper reinforcement	\$ 356.00 X
1	Rear bumper side retainer	\$ 38.50 X
2	Rear bumper PDC sensors	\$ 373.00 X
1	Rear bumper lower diffuser	\$ 298.50
1	Rear fender -LH	\$ 889.60 X
1	Rear wheel hub with bearing	\$ 289.50 X
1	Rear shock absorber	\$ 221.60 X
		\$ 4,052.80
	Less 10%	\$ 405.28
		\$ 3,647.52

<u>SPECIAL NETT ITEMS</u>		
1	Rear bumper clip (1 set)	\$ 50.00 ✓
1	Rear tyre	\$ 400.00 X
1	Rear wheel rim -LH	\$ 750.00 X
		\$ 1,200.00

<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 50
4	To remove and refit rear undercarriage.	\$ 300.00 X
5	To conduct wheel alignment.	\$ 150.00 X
6	To apply undercoating.	\$ 100.00 X
7	Panel beating.	\$ 1,400.00 200
8	To re-spray painting on the affected areas.	\$ 1,200.00 380
		\$ 3,560.00

GRAND TOTAL :

\$ 8,407.52

2-1038.50
100
934.65