



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY			Ref: CC4/ASM23000344/Upa3q2 Date: 11/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 775Y	Veh. Inspected	SMW 5618K
	Policy No.	P2478220	Coverage (\$)	0.00
	Claim No.	S3M04HRW	Excess (\$)	0.00
	Assign From		Assign Date	10/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TOURAN (A)	c.c	5198
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WVGZZZ1TZFW038952	Colour	WHITE
	Odometer	176671 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40Z R18	FALKEN	5 mm
	L/H Front Tyre	225/40Z R18	FALKEN	5 mm
	R/H Rear Tyre	225/40Z R18	FALKEN	5 mm
	L/H Rear Tyre	225/40Z R18	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/01/2023	Inspection Date	11/01/2023
	Survey held at	SM SPRAY PAINTING PTE LTD NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	