

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM23000344/UP93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMW 5618Kat Workshop m/s SM spray

of _____

Insured: SHA7754

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8 36k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 436kDate: _____ Person Contacted: 274924274

Vehicle: IN / OUT

Date / Time Action / Instruction 27/13k14/1/23 4/5 @ 1200 informed WendyVeh No: SMW5618K Yr Regn: 30/03/15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Volkswagen Touran c.c. 1598Colour: white A/C: Insured / Std / NI / NASp. Reading: 176671 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVGxxxITzFW038952Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40zr18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Z P UdenFront fr Rear 5

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 5 mm L/Bal. 5 mmD.O.A. 08/01/23 D.O.I. 11/1/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S M SPRAY PAINTING

25 Kaki Bukit Road 4 #08-30
synergy Singapore 417800

SMW5618K VOLKSWAGEN TOURAN
DOA : 08-01-2023

not Allowed
for margin
2/ \$11200/
3 days
to high the price
11/1/23
90096608

1	REAR BUMPER	11	1	\$	1,500.70	X
2	REAR BUMPER SIDE RETAINER	11	1	\$	100.70	X
3	REAR BUMPER CLIPS	11	1SET	\$	50.00	X
4	REAR FENDER	11	1	\$	1,299.10	X
5	REAR FENDER SIDE SHIELD	11	1	\$	198.70	X
6	REAR FENDER SIDE SHIELD CLIPS	11	1SET	\$	50.00	X
7	REAR FENDER INNER TRIM	11	1	\$	374.90	X
8	REAR FENDER INNER TRIM CLIPS	11	1SET	\$	50.00	X
9	REAR 1/4 GLASS MOULDING	11	1	\$	120.20	X
10	REAR DOOR	11	1	\$	1,725.00	X
11	REAR DOOR WEATHER STRIP	11	1	\$	215.00	X
12	REAR SHOCK ABSORBER	11	1	\$	300.86	X
13	REAR LOWER ARM	11	1	\$	470.64	X
14	REAR KNUCKLE ARM	11	1	\$	840.70	X
15	REAR WHEEL BEARING	11	1	\$	330.10	X
16	REAR TRAILING ARM	11	1	\$	375.54	X
17	REAR TRACK ARM	11	1	\$	296.32	X
18	REAR TRACK ARM LINK	11	1	\$	249.20	X

TOTAL PARTS	\$	8,547.66
10%	\$	854.77
	\$	7,692.89

1	REAR SPORT RIM	11	1	\$	600.00	X
2	REAR TYRE	11	1	\$	400.00	X
3	REAR 1/4 GLASS SEALANT	11	1	\$	100.00	X
4	REAR 1/4 GLASS SPONGE	11	1	\$	80.00	X

TOTAL PARTS	\$	1,180.00
-------------	----	----------

1	LABOUR	\$	1,000.00	400
2	SPRAY PAINTING	\$	1,000.00	400
3	SPRAY ANIT RUST	1 1 \$	100.00	X
4	CHECK WIRING	1 1 \$	50.00	X
5	WHEEL ALIGNMENT TEST	\$	150.00	60
6	REMOVE, RENEW AND REFIT REAR UNDER CARRIAGE	1 1 \$	600.00	X
7	REMOVE AND REFIT REAR REVERSE SENSOR	1 1 \$	50.00	X
8	REMOVE AND REFIT REAR UPHOLSTER	1 1 \$	300.00	X
9	REDO SEALANT ON GAP	1 1 \$	100.00	X
10	REMOVE, RENEW AND REFIT REAR RIMS FOR BALANCING	1 1 \$	50.00	X
11	REMOVE, RENEW AND REFIT REAR TYRE	1 1 \$	50.00	X
12	CONDUCT WATER LEAKAGE TEST	1 1 \$	50.00	X
13	DIGNOSTIC & RESET FAULT CODE	1 1 \$	300.00	X
14	REMOVE, RENEW AND REFIT FUEL TANK	1 1 \$	100.00	X
15	REMOVE, RENEW AND REFIT REAR 1/4 GLASS	1 1 \$	100.00	X
16	TO REMOVE AND REFIT ALL FITTING TO REAR DOOR	1 1 \$	150.00	X

TOTAL LABOUR \$ 4,150.00

TOTAL AMOUNT \$ 13,022.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1540
202
1732