

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 08/01/2023

TP Veh Reg No: SLB194X

Estimate No: ES2300138/AMK

Date: 13 Feb 2023

Policy No: DMHCSNW00006882200

Veh Reg No: SMX8392K

Make/Model: MITSUBISHI ATTRAGE
1.2

Chassis No: MMBSTA13AMH002992

Engine No: 3A92UJT9424

Reg. Date: 01/02/2021

Estimate Repair Cost to Vehicle No :SMX8392K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	589.00	1 PC	589.00	✓
2 REAR BUMPER RH SIDE RETAINER	36.00	1 PC	36.00	✓
3 REAR BUMPER CLIP	5.00	5 PC	25.00	✓
			650.00	
		Less 10%	65.00	585.00
Special Net				
4 REVERSE SENSOR	200.00	1 SET	200.00	?
			200.00	200.00
Labour				
5 REMOVE & REFIX REAR BUMPER & ATTACHMENTS;KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	400.00	1 LA	400.00	200
6 PUTTY & RESPRAY REAR BUMPER & PARKING SENSOR,REAR END PANEL & ALL AFFECTED AREAS	400.00	1 LA	400.00	200
			800.00	800.00
			Total	S\$ 1,585.00
			Add GST @ 8%	126.80
			Total Amount Payable	S\$ 1,711.80

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dorlyn
AUTHORISED SIGNATURE