

ASS. REC BY: Touffan

REF:

CSG/115.23 000348/Twy3

ASSIGNMENT

2031 Apr 1
2011 April

From: _____ Date: _____
Estimated Cost: _____
BD TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 8600
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 896K.
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKA8553H Yr Regn: 2011 April
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Mercedes Benz E250 C.C. 1796
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 233158 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2120472A387296
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S Rim / STD A/Rim or _____
Tyre Size: F: 225/55R16
R: _____
BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.L. _____
Survey held at Cheng Hoe.
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)

Survey Fee:	
Transportation:	
\$ + PS \$:	
Photos	
Others	

Report Format: _____
Lump Sum / L.B.R. / P. _____



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/ALLIANZ
Policy No:	SP2001529616-01	Date of Loss:	01/01/2023
Vehicle Reg. No.:	SKA3553H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HENG BOO CHYE		
Driver:	HENG BOO CHYE		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	07/04/2011
Vehicle Colour:	Black		
Engine No:	27186030188639	Chassis No:	WDD2120472A387296
Odometer:	232929 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	1,353.00
Miscellaneous Items	35.00
Labour	830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,218.00
+ GST 8.00% (\$\$)	177.44
Nett Amount (\$\$)	2,395.44

This claim is handled by: EFEEEDA BINTE MOHAMED OTHMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts: M1-COUPE MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SKA8553H/10/01/2023 14:33
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*785.00 F
2	1		*1 PC FRT GRILLE ASSY	0.00	0.00	*445.00 F
F=Franchise part.						
Sub Total (S\$)						1,230.00
+ Margin on L,N Items 10.00% (S\$)						123.00
Total Parts (S\$)						1,353.00

Cheng Hoe Motor Pte Ltd/SKA8553H/10/01/2023 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT NUMBER PLATE	35.00
Sub Total (S\$)			<u>35.00</u>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE DAMAGE PARTS AND ATTACHMENTS. PANEL BEAT AND REPAIR RH HEADLAMP PANEL, INNER FEND AND BONNET. REALIGN AND REPLACE FRT END DAMAGE BODY PARTS.	New 300	450.00
2	SPRAY PAINTING ON FRT BUMPER, FRT END TOP PANEL.	New 300	380.00
Gross Labour Cost (S\$)			<u>830.00</u>

Cheng Hee Motor Pte Ltd/SKA8553H/10/01/2023 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfimi 97495749
111123 C 1030 ~
Not Authorise Ex \$600
Revert
Lumpsum Repair after repair
2 days - 3 days
tanfimi@khareto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: