

(08/11/23) wef

ASS. R. EC. BY: /

Tanfikh

REF:

CS/LIP23000356/Tvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMH 7244X

Policy No. _____

Claims No. BVS23/0019

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$60K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLA3059P Yr Regn: 26/2/2016

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan 14TS c.c. 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 70383 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVGZZZ5NZGW065774

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In Order / Jammed / Leaked / Burnt orBrake: ☒ In Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 255/45 R18

R: _____

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. 5 mm L/Bal. 6 mm

D.O.A. 27/12/2022 D.O.I. 11/1/2023

Survey held at Xin Yun Auto

Des. of Damages: Frt / ☒ Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Net value \$28,000

4/4/23 Lump Sum \$4100 confirmed by email (Red 20,720, 83%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: 2

2) 5/4/23-typist

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____) TOTAL

Report Format: TP

Lump Sum / t.B.t: (\$ 4100)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

D.O.A. : 27/12/2022
Liberty (TaurPich) survey on 11/1/2023.

Net value?

- Taufik marking?

- Veron.



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLA3059P \ VW TIGUAN

WVG ZZZ 5N ZGW 065 114

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,829.00
2	2	Front bumper side bracket	\$ 240.00
3	2	Rear bumper reflector	\$ 220.00
4	1	Rear lower lip	\$ 980.00
5	1	Lower lip center trim cover	\$ 780.00
6	1	Rear fender light	\$ 950.00
7	1	Rear tailgate light	\$ 780.00
8	1	Rear air vent	\$ 95.00
9	2	Rear bumper lower lining-bumper joint to wheel arch	\$ 700.00
10	1	Rear top cover garnish	\$ 380.00
11	1	Rear left wheel arch trim cover	\$ 680.00
12	1	Reinforcement	\$ 850.00
13	1	Rear tailgate	\$ 2,286.00
14	1	Rear end panel	\$ 1,200.00
15	1	Tailgate logo	\$ 190.00
16	1	Rear center logo emblem	\$ 105.00
17	2	Tailgate damper	\$ 600.00
18	1	Cable harness	\$ 450.00
19	1	Tailgate lock mechanism	\$ 280.00
20	1	Tailgate rubber garnish/ weatherstrip	\$ 250.00
21	2	Rear tailgate no plate lamp	\$ 160.00
22	1	Rear end top garnish trim	\$ 280.00
23	1	Keyless sensor	\$ 350.00
24	1	Rear spoiler	\$ 980.00
25	2	Rear seat side cover trim	\$ 300.00
26	1	Exhaust	\$ 650.00
27	1	Tow cover	\$ 95.00
Parts Sub-total			\$ 16,660.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLA3059P VW TIGUAN

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	--------------------------

Special Nett Items

1	12	Rear bumper clips	\$ 120.00	50 NEC
2	10	Rear bumper lower lip clips	\$ 80.00	20 NEC
3	8	Rear tailgate inner board clips	\$ 80.00	XNN
4	10	Rear end panel clips	\$ 80.00	XNS
5	8	Rear end panel top garnish clips	\$ 60.00	20 NEC
6	6	Rear fender light clips	\$ 60.00	XNN
7	20	Both fender inner trim clips	\$ 120.00	XNN
8	12	Lower middle trim clips	\$ 120.00	XNN
9	1	Windscreen seal	\$ 150.00	XNN
10	4	Rear bumper sensors	\$ 800.00	Short cut
11	1	Rear number plate	\$ 90.00	XNN
12	1	Rear number plate casing	\$ 40.00	XNN

Special Nett Items Total

\$ 1,800.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SLA3059P

Modle: VW TIGUAN

No	Description	Labour Charges	
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00	30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 250.00	30
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 2,000.00	600
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side in & out, touch up fender	\$ 2,000.00	600
5	Carry out wheel alignment	\$ 120.00	X
6	Removing and installing rear fender compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00	X
7	Transferring tailgate /bootlid lock mechanism, trimming etc to the new tailgate /bootlid	\$ 120.00	X
8	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00	X
9	Checking central lock system for proper function	\$ 120.00	X
10	Removing and installing rear fender internal garnish and trimming to facilitate the necessary repair	\$ 120.00	X
11	Removing & installing rear window /windscreen glass to facilitate repair	\$ 150.00	X
12	To remove and install rear camera	\$ 80.00	X
13	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00	X
14	Water test after accident repair body work	\$ 120.00	X
15	Paint protection coating for accident affected areas	\$ 300.00	X
16	Carry out diagnosis check including cleaning accident fault code	\$ 150.00	100
17	Coding or programming	\$ 300.00	X
Total labour :		\$ 6,360.00	

24,820

Lumpsum Repair
0.5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

> Back to OneMotoring

D.O.A.: 27/12/2022
Bal.: 3yrs 2mths.
M.V.: \$60,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 947C

Vehicle Details

Vehicle No.: SLA3059P
Vehicle to be Exported: No
Intended Deregistration Date: 06 Apr 2023
Vehicle Make: VOLKSWAGEN
Vehicle Model: TIGUAN 1.4 TSI AT BMT 5N22QY
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: CTH239959
Chassis No.: WVGZZZ5NZGW065774
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$27,534.00
Original Registration Date: 26 Feb 2016
First Registration Date: 26 Feb 2016
Transfer Count: ②
Actual ARF Paid: \$30,548.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Feb 2026
PARF Rebate Amount: \$18,328.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,970.00
COE Rebate Amount: \$13,573.00
Total Rebate Amount: \$31,901.00

The information contained herein is correct as at 31 Mar 2023

OK

15,430

14,740 (3)