



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23000358/Uvy3e2 Date: 03/02/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 5692G	Veh. Inspected	SCP 210R	
Policy No.	P10507892R01	Coverage (\$)	0.00	
Claim No.	C10019748 /KY	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	11/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.4 (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053BK4007037832	Colour	GREY	
Odometer	110559 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	6 mm	
L/H Front Tyre	215/60 R16	FALKEN	6 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2023	Inspection Date	11/01/2023	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	