



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23000361/Uny3e2 Date: 11/05/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMK 4646Z	Veh. Inspected	SLV 1047B
Policy No.	P10751080R00	Coverage (\$)	0.00
Claim No.	C10019759 /JT	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	11/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	BYD E6H	c.c	0
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	LC0CE4DB6H1026308	Colour	WHITE
Odometer	251442 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/65 R17	SAILUN	7 mm
L/H Front Tyre	225/65 R17	SAILUN	7 mm
R/H Rear Tyre	225/65 R17	SAILUN	7 mm
L/H Rear Tyre	225/65 R17	SAILUN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	09/01/2023	Inspection Date	12/01/2023
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	