

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Uny3  
CS/AG/123000361/443

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
	6

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C1336

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 29898

Date / Time

Action / Instruction

CNV 22/1/23

high mileage

29/12/22

nett 2802

8/5/23 1/5 \$ 14,000 in hand Alex (red, \$17,734.68, 56%)

Veh No:

SLV1047B

Yr Regn:

21/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BYD E6H

Electric

c.c 90 kW

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

25/442

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LC0CE4DB6H1026308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sai/41

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

09/01/23

12/1/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

7

1) 08/05/23

☐

Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

☐

Weekend (\$

TOTAL

# CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: SLV1047B

MAKE & MODEL: BYD E6H

DOA: 09.01.2023

CLAIM TYPE: TP CLAIM

not Affected  
OKK  
12/1/23  
4/5 & 14,000  
7 days.

## ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$ 2,248.00	Dis ✓
FRONT BUMPER RETAINER LH	1	\$ 79.00	Sub ✓
FRONT BUMPER RETAINER RH	1	\$ 79.00	Sub ✓
FRONT BUMPER BRACKET LH	1	\$ 79.00	NS X
FRONT BUMPER BRACKET RH	1	\$ 79.00	NS X
FRONT BUMPER REINFORCEMENT	1	\$ 589.00	Sub ✓
FRONT BUMPER REINFORCEMENT BRACKET RH	1	\$ 387.00	Sub ✓
FRONT BUMPER LOGO	1	\$ 107.00	NS ✓
FRONT BUMPER LOWER GRILLE	1	\$ 258.00	Tw ✓
FRONT BUMPER CENTRE GRILLE	1	\$ 859.00	CM ✓
FRONT BUMPER GRILLE LH	1	\$ 248.00	11 X
FRONT BUMPER GRILLE RH	1	\$ 248.00	11 X
FRONT BUMPER FOG LAMP LH	1	\$ 325.20	NS X
FRONT BUMPER FOG LAMP RH	1	\$ 325.20	NS X
FRONT BUMPER REFLECTOR LH	1	\$ 89.00	11 X
FRONT BUMPER REFLECTOR RH	1	\$ 89.00	11 X
FRONT BUMPER SENSORS	2	\$ 450.00	11 X
FRONT BONNET	1	\$ 1,974.00	Sub ✓
FRONT BONNET HINGE	2	\$ 250.00	11 X
FRONT Support panel	1	\$ 508.00	Sub ✓
FRONT BONNET LOCK	1	\$ 458.00	FW ✓
RADIATOR	1	\$ 1,343.00	Sub/Bus ✓
HEADLAMP LH	1	\$ 2,250.00	CM ✓
HEADLAMP BRACKET LH	1	\$ 159.00	NS X
HEADLAMP RH	1	\$ 2,250.00	CM ✓
HEADLAMP BRACKET RH	1	\$ 159.00	NS X
REAR BUMPER	1	\$ 1,890.00	Dis ✓
REAR BUMPER RETAINER LH	1	\$ 87.00	Sub ✓
REAR BUMPER RETAINER RH	1	\$ 87.00	Sub ✓
REAR BUMPER BRACKET LH	1	\$ 87.00	NS X
REAR BUMPER BRACKET RH	1	\$ 87.00	NS X
REAR BUMPER LOWER GRILLE	1	\$ 758.00	FW ✓
REAR BUMPER REFLECTOR INNER LH	1	\$ 158.00	CM ✓
REAR BUMPER REFLECTOR INNER RH	1	\$ 158.00	11 X
REAR BUMPER REFLECTOR LH	1	\$ 89.00	11 X
REAR BUMPER REFLECTOR RH	1	\$ 89.00	11 X
REAR BUMPER REINFORCEMENT	1	\$ 575.00	Sub ✓
REAR END PANEL	1	\$ 758.00	Sub ✓
REAR END PANEL TOP GARNISH	1	\$ 422.80	11 X
TAILGATE	1	\$ 2,567.00	11 X
TAILGATE WEATHERSTRIP	1	\$ 372.00	11 X
TAILGATE HINGE	2	\$ 176.00	11 X
TAILGATE ABSORBER	2	\$ 560.00	11 X
TAILGATE LOGO	1	\$ 107.00	11 X
TAILGATE LOCK	1	\$ 478.00	11 X

\$ 25,395.20

LESS 10% \$ 2,539.52

13246

SUB TOTAL \$ 22,855.68

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER CLIP	1 SET	\$ 50.00	new ✓
FRONT NUMBER PLATE	1	\$ 90.00	new 40
FRONT BONNET INSULATOR CLIP	1 SET	\$ 50.00	17 X
REAR BUMPER CLIP	1 SET	\$ 50.00	new ✓
REAR NUMBER PLATE	1	\$ 90.00	17 X
REAR END PANEL TOP GARNISH CLIP	1 SET	\$ 50.00	17 X
REVERSE SENSOR	1 SET	\$ 880.00	no function 250
JOINT SEALANT <i>end panel</i>	1	\$ 120.00	new 50
SUB TOTAL		\$ 1,380.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK FRONT AND REAR WIRING AND LIGHTING SYSTEM	1	\$ 200.00	30
REMOVE AND RENEW FRONT AND REAR SENSOR	1	\$ 200.00	50
REMOVE AND REFIT <del>FRONT AND REAR</del> LINING, TRIM AND GARNISH	1	\$ 300.00	80
PANEL BEATING ON FRONT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	600
PANEL BEATING ON REAR AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	800
SPRAY PAINTING ON FRONT AFFECTED AREAS	1	\$ 1,200.00	800
SPRAY PAINTING ON REAR AFFECTED AREAS	1	\$ 1,200.00	1000
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	90

SUB TOTAL \$ 5,600.00

GRAND TOTAL \$ 29,835.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-18/55  
102  
13639.5  
440  
3460  
17528.5  
(1405)

# CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: SLV1047B

MAKE & MODEL: BYD E6H

DOA: 09.01.2023

CLAIM TYPE: TP CLAIM

## ESTIMATION QUOTE

SUPPLEMENTARY	QTY	PRICE (\$)	REMARKS
1pc Condenser Sent/Run	1	\$ 958.00	✓
1pc Air con pipe one @ 211	✓		
2pc Rear fender undershields @ 11542-230 2pc ✓			
1pc Tail lamp 1/5 @ 500 one	QTY	PRICE (\$)	REMARKS
	1	\$	