

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

✓
19/1/2023 - Whatapp to
Adrian

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1177/2022/EQ

18-Jan-23

CHANG

1 of 1

SNB 1512 G

AUDI A4 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO CUT OUT AND WELD REINFORCEMENT FOR LH REAR SIDE PANEL.	\$ 1,000.00	
2	TO RESPRAY SPARE WHEEL HOUSING.	\$ 1,100.00	
Parts			
1	REINFORCEMENT FOR SIDE PANEL - LH	\$ 243.00	
2	TELEPHOPNE AERIAL	\$ 197.00	
3	RETAINER FOR AERIAL	\$ 30.00	
4	METAL FILLER POWDER	\$ 280.00	
5	CAVITY WAX	\$ 140.00	
GRAND TOTAL			\$ 2,990.00

For Premium Automobiles Pte Ltd

* Additional 5 days-




Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N	TBC	
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	S/N \$	360.00	✓
3	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	✓
4	TO DISLodge ANS REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, USE AND RELAY TRAYS BATTERY MANAGER, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,700.00	?
5	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEAT BELTS.	S/N \$	1,800.00	✓
6	TO DISMANTLE REAR BUMPER AND REAR LID. (CUT OUT AND WELD REAR OUTER AND INNER REAR CROSS PANELS. REPAIR LHS REAR FENDER) RENEW REAR BUMPER AND REAR LID, ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,550.00	
TOTAL LABOUR CHARGES		:	\$ 8,690.00	

1250 End Panel
Repairs

2000 End Panel
Replaced.

5x500 (End panel inner/outer)
= 2500

0.5x500 (LHS rear fender)
= 250

2750

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, END PANELLING AND LHS REAR FENDER. TO CARRY OUT STONE CHIP TREATMENT.	\$ 3,700.00	1650 + 550
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,582.00	

Car-in

13/1/23

wp: 57019.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ATG - Adrian
- 7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dented</i>	1	\$ 2,493.00	✓
2	REAR BUMPER FIXING PARTS <i>New</i>	1	\$ 173.00	X
3	REAR BUMPER SECURING STRIP - LOWER }?	1	\$ 125.00	?
4	REAR BUMPER SECURING STRIP - UPPER }	1	\$ 249.00	?
5	REAR BUMPER SPOILER <i>Distorted</i>	1	\$ 276.00	✓
6	REAR BUMPER BRACKET (LH / RH) ?	2	\$ 456.00	?
7	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 1,131.00	?
8	REAR BUMPER IMPACT BAR GASKET - LH / RH ?	2	\$ 32.00	?
9	REAR BUMPER GUIDE SECTION - LH / RH UPPER ?	2	\$ 100.00	?
10	REAR BUMPER GUIDE SECTION - LH / RH LOWER ?	2	\$ 52.00	?
11	REAR BUMPER HOLDING STRAP (LH / RH) ?	2	\$ 188.00	?
12	EXHAUST TAIL PIPE TRIM (LH / RH) <i>New</i>	2	\$ 766.00	X
13	REAR BUMPER REFLECTOR - LH / RH <i>LH cancelled</i>	2	\$ 96.00	48
14	REAR BUMPER REFLECTOR (LH / RH) <i>New</i>	2	\$ 96.00	+
15	REAR PARKING AID SENSOR - INNER / OUTER <i>New</i>	2	\$ 531.00	+
16	REAR PARKING AID SEAL RING <i>New</i>	4	\$ 10.00	+
17	REAR LID <i>Dented</i>	1	\$ 3,458.00	✓
18	REAR LID ATTACHMENT PARTS <i>New</i>	1	\$ 429.00	+
19	REAR LID HINGE - LH / RH <i>New</i>	2	\$ 510.00	+
20	REAR LID LOCK <i>New</i>	1	\$ 218.00	X
SUB TOTAL SPARE PARTS		:	\$ 11,389.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK COVER CAP ?	1	\$ 8.00	+
22	REAR LID LOCK STRIKER } NY	1	\$ 37.00	+
23	REAR LID FLAP GASKET } m	1	\$ 229.00	+
24	PACKING ADHESIVE m	1	\$ 21.00	✓
25	AUDI EMBLEM } Nee	1	\$ 144.00	✓
26	"A4" INSCRIPTION } Nee	1	\$ 104.00	✓
27	REAR OUTER TAIL LIGHT - LH xee m	1	\$ 1,135.00	+
28	REAR INNER TAIL LIGHT - LH he m	1	\$ 1,135.00	+
29	REAR OUTER TAIL LIGHT TRIM - LH } xee m	1	\$ 34.00	+
30	REAR INNER TAIL LIGHT TRIM - LH	1	\$ 34.00	+
31	REAR OUTER TAIL LIGHT - RH xee m	1	\$ 1,135.00	+
32	REAR INNER TAIL LIGHT - RH c m d	1	\$ 1,135.00	✓
33	REAR OUTER TAIL LIGHT TRIM - RH xee m	1	\$ 34.00	+
34	REAR INNER TAIL LIGHT TRIM - RH xee m	1	\$ 34.00	+
35	REAR WARNING TRIANGLE xee m	1	\$ 213.00	+
36	REAR WARNING TRIANGLE RETAINER xee m	1	\$ 65.00	+
37	REAR LID TRIM PANEL xee m	1	\$ 365.00	+
38	REAR CROSS PANEL ?	1	\$ 274.00	?
39	REAR CROSS PANEL REINFORCEMENT ?	1	\$ 532.00	?
40	REAR CROSS PANEL TRIM De l m d	1	\$ 185.00	✓
SUB TOTAL SPARE PARTS		:	\$ 6,853.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	THREE-POINT AUTOMATIC SEAT BELT - LH / RH <i>Activated</i>	2	\$	2,454.00 ✓
42	SEAT BELT HEIGHT ADJUSTER - LH / RH <i>Not in</i>	2	\$	384.00 X
43	AIRBAG CONTROL UNIT <i>Activated</i>	1	\$	2,364.00 ✓
44	CENTRAL PROTECTION <i>Activated</i>	1	\$	590.00 ✓
45	REAR TAILGATE CHROME TRIM STRIP - CENTER <i>Defect</i>	1	\$	272.00 ✓
46	ACRYLIC SEALANT ?	S/N	\$	180.00 ?
47	STONE CHIP ?	S/N	\$	180.00 ?
48	REAR NO PLATE <i>Not in</i>	S/N	\$	80.00 X
49	SUNDRIES ?		\$	300.00 ?
TOTAL SPARE PARTS		:	\$	25,046.00
TOTAL LABOUR CHARGES		:	\$	12,582.00
GRAND TOTAL		:	\$	37,628.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.