

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1177/2022/EQ
DATE : 3-Jan-23
WIP : 57019

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SARAVANAN SUDAKAR
ADDRESS : BLK 1 BUKIT BATOK STREET 25
#11-03
SINGAPORE 658882
TELEPHONE : HP +65 84797783
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210085012
VEHICLE NO : **SNB 1512 G**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2021
ENGINE NO : DEM 029139
CHASSIS NO : WAUZZZF45MA028692
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-22
PLACE OF ACCIDENT : PIE AFTER (UPPER JURONG ROAD) BEFORE
SINGAPORE DISCOVERY CENTER

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N TBC	
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	S/N \$ 360.00	✓ ✓
3	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	✓ ✓
4	TO DISLodge ANS REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, USE AND RELAY TRAYS BATTERY MANAGER, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,700.00	? ✓ 1700 <i>ll's</i>
5	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEAT BELTS.	S/N \$ 1,800.00	✓ ✓
6	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER AND INNER REAR CROSS PANELS. REPAIR LHS REAR FENDER. RENEW REAR BUMPER AND REAR LID, ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,550.00	<i>ll's</i> 1250 End Panel Repair 2000 End Panel Replaced.
TOTAL LABOUR CHARGES		: \$ 8,690.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
* 7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, END PANELLING AND LHS REAR FENDER. TO CARRY OUT STONE CHIP TREATMENT.	\$ 3,700.00	1680 2200
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ 865
TOTAL LABOUR CHARGES		: \$ 12,582.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehnd</i>	1	\$ 2,493.00	✓ 1994.4
2	REAR BUMPER FIXING PARTS <i>New</i>	1	\$ 173.00	X X
3	REAR BUMPER SECURING STRIP - LOWER <i>} New</i>	1	\$ 125.00	? ✓ 100 ✓
4	REAR BUMPER SECURING STRIP - UPPER	1	\$ 249.00	? ✓ 198.8 ✓
5	REAR BUMPER SPOILER <i>Distorted</i>	1	\$ 276.00	✓ 220.8
6	REAR BUMPER BRACKET - LH / RH <i>Best</i>	2	\$ 456.00	? ✓ 182 ✓
7	REAR BUMPER REINFORCEMENT BEAM <i>Best</i>	1	\$ 1,131.00	? ✓ 904.8 ✓
8	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>Not new</i>	2	\$ 32.00	? X
9	REAR BUMPER GUIDE SECTION - LH / RH UPPER <i>Not new</i>	2	\$ 100.00	? X
10	REAR BUMPER GUIDE SECTION - LH / RH LOWER <i>By 2</i>	2	\$ 52.00	? ✓ 40.32 ✓
11	REAR BUMPER HOLDING STRAP - LH / RH <i>By d</i>	2	\$ 188.00	? ✓ 74.8 ✓
12	EXHAUST TAIL PIPE TRIM - LH / RH <i>Not new DM</i>	2	\$ 766.00	X ✓ 612 ✓
13	REAR BUMPER REFLECTOR - LH / RH <i>Not new</i>	2	\$ 96.00	48 76.48
14	REAR BUMPER REFLECTOR - LH / RH <i>Not new</i>	2	\$ 96.00	+
15	REAR PARKING AID SENSOR - INNER / OUTER <i>Not new</i>	2	\$ 531.00	+
16	REAR PARKING AID SEAL RING <i>Not new</i>	4	\$ 10.00	+
17	REAR LID <i>Dented</i>	1	\$ 3,458.00	✓ 2766.4
18	REAR LID ATTACHMENT PARTS <i>Not new</i>	1	\$ 429.00	+
19	REAR LID HINGE - LH / RH <i>Not new</i>	2	\$ 510.00	+
20	REAR LID LOCK <i>Not new</i>	1	\$ 218.00	+
SUB TOTAL SPARE PARTS		:	\$ 11,389.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK COVER CAP <i>HP</i>	1	\$ 8.00 +	
22	REAR LID LOCK STRIKER <i>HP</i>	1	\$ 37.00 +	
23	REAR LID FLAP GASKET <i>HP</i>	1	\$ 229.00 + ✓	193.2 ✓
24	PACKING ADHESIVE <i>HP</i>	1	\$ 21.00 ✓	16.8
25	AUDI EMBLEM <i>HP</i>	1	\$ 144.00 ✓	115.2
26	"A4" INSCRIPTION <i>HP</i>	1	\$ 104.00 ✓	83.2
27	REAR OUTER TAIL LIGHT - LH <i>HP</i>	1	\$ 1,135.00 + ✓	908 ✓
* 28	REAR INNER TAIL LIGHT - LH <i>HP</i>	1	\$ 1,135.00 + ✓	908 ✓
29	REAR OUTER TAIL LIGHT TRIM - LH <i>HP</i>	1	\$ 34.00 + ✓	26.4 ✓
30	REAR INNER TAIL LIGHT TRIM - LH <i>HP</i>	1	\$ 34.00 +	
31	REAR OUTER TAIL LIGHT - RH <i>HP</i>	1	\$ 1,135.00 +	
32	REAR INNER TAIL LIGHT - RH <i>HP</i>	1	\$ 1,135.00 ✓	908
33	REAR OUTER TAIL LIGHT TRIM - RH <i>HP</i>	1	\$ 34.00 +	
34	REAR INNER TAIL LIGHT TRIM - RH <i>HP</i>	1	\$ 34.00 +	
35	REAR WARNING TRIANGLE <i>HP</i>	1	\$ 213.00 +	
36	REAR WARNING TRIANGLE RETAINER <i>HP</i>	1	\$ 65.00 +	
37	REAR LID TRIM PANEL <i>HP</i>	1	\$ 365.00 +	
38	REAR CROSS PANEL <i>Dented.</i>	1	\$ 274.00 ? ✓	218.8 ✓
39	REAR CROSS PANEL REINFORCEMENT <i>Dented.</i>	1	\$ 532.00 ? ✓	425.2 ✓
40	REAR CROSS PANEL TRIM <i>Dented.</i>	1	\$ 185.00 ✓	148
SUB TOTAL SPARE PARTS		:	\$ 6,853.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	THREE-POINT AUTOMATIC SEAT BELT - LH / RH <i>Activated</i>	2	\$ 2,454.00	✓ 1963.2
42	SEAT BELT HEIGHT ADJUSTER - LH / RH <i>Activated</i>	2	\$ 384.00	x. ✓ 307.2 ✓
43	AIRBAG CONTROL UNIT <i>Activated</i>	1	\$ 2,364.00	✓ 1,891.2
44	CENTRAL PROTECTION <i>Activated</i>	1	\$ 590.00	✓ 472
45	REAR TAILGATE CHROME TRIM STRIP - CENTER <i>Delint</i>	1	\$ 272.00	✓ 217.6
46	ACRYLIC SEALANT <i>Neu</i>	S/N	\$ 180.00	7 ✓ 180 ✓
47	STONE CHIP <i>Neu</i>	S/N	\$ 180.00	7 ✓ 180 ✓
48	REAR NO PLATE <i>Not neu</i>	S/N	\$ 80.00	X. X
49	SUNDRIES <i>Neu</i>		\$ 300.00	? ✓ 64.96 ✓
TOTAL SPARE PARTS		:	\$ 25,046.00	
TOTAL LABOUR CHARGES		:	\$ 12,582.00	
GRAND TOTAL		:	\$ 37,628.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 10/01/23
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : 12 Days H.S.
xol Authorised, 07 Days End Panel Repair
10 Days End Panel Replaced

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT