

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1177/2022/EQ
DATE : 3-Jan-23
WIP : 57019

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian

12 days exclude 2 PH & 1 Sunday

Johnny Boo 29 Mar 23

OWNER'S NAME : MR SARAVANAN SUDAKAR
ADDRESS : BLK 1 BUKIT BATOK STREET 25
#11-03
SINGAPORE 658882
TELEPHONE : HP +65 84797783
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210085012
VEHICLE NO : **SNB 1512 G**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/7/2021
ENGINE NO : DEM 029139
CHASSIS NO : WAUZZZF45MA028692
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-22
PLACE OF ACCIDENT : PIE AFTER (UPPER JURONG ROAD) BEFORE
SINGAPORE DISCOVERY CENTER

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N	TBC	
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
3	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$ 280.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, USE AND RELAY TRAYS BATTERY MANAGER, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,700.00	\$ 1,700.00
5	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEAT BELTS.	S/N \$	1,800.00	\$ 1,800.00
6	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER AND INNER REAR CROSS PANELS. REPAIR LHS REAR FENDER. RENEW REAR BUMPER AND REAR LID, ALIGN TO POSITION. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,550.00	\$ 2,750.00
TOTAL LABOUR CHARGES		:	\$ 8,690.00	\$ 6,890.00



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 1512 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, END PANELLING AND LHS REAR FENDER. TO CARRY OUT STONE CHIP TREATMENT.	c/f	\$ 3,700.00	\$ 6,890.00
8	ADD LABOUR		\$ 2,100.00	\$ 1,050.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 14,682.00	\$ 10,332.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,493.00	\$	1,994.40
2	REAR BUMPER FIXING PARTS	1	\$ 173.00		
3	REAR BUMPER SECURING STRIP - LOWER	1	\$ 125.00	\$	100.00
4	REAR BUMPER SECURING STRIP - UPPER	1	\$ 249.00	\$	198.80
5	REAR BUMPER SPOILER	1	\$ 276.00	\$	220.80
6	REAR BUMPER BRACKET - LH / RH	2	\$ 456.00	\$	182.00
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	\$	904.80
8	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 32.00		
9	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$ 100.00		
10	REAR BUMPER GUIDE SECTION - LH / RH LOWER	2	\$ 52.00	\$	40.32
11	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 188.00	\$	74.80
12	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 766.00	\$	612.00
13	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00	\$	76.48
14	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00		
15	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00		
16	REAR PARKING AID SEAL RING	4	\$ 10.00		
17	REAR LID	1	\$ 3,458.00	\$	2,766.40
18	REAR LID ATTACHMENT PARTS	1	\$ 429.00		
19	REAR LID HINGE - LH / RH	2	\$ 510.00		
20	REAR LID LOCK	1	\$ 218.00		
SUB TOTAL SPARE PARTS		:	\$ 11,389.00	\$	7,170.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>7,170.80</i>
21	REAR LID LOCK COVER CAP	1	\$ 8.00		
22	REAR LID LOCK STRIKER	1	\$ 37.00		
23	REAR LID FLAP GASKET	1	\$ 229.00	<i>\$</i>	<i>193.20</i>
24	PACKING ADHESIVE	1	\$ 21.00	<i>\$</i>	<i>16.80</i>
25	AUDI EMBLEM	1	\$ 144.00	<i>\$</i>	<i>115.20</i>
26	"A4" INSCRIPTION	1	\$ 104.00	<i>\$</i>	<i>83.20</i>
27	REAR OUTER TAIL LIGHT - LH	1	\$ 1,135.00	<i>\$</i>	<i>908.00</i>
28	REAR INNER TAIL LIGHT - LH	1	\$ 1,135.00	<i>\$</i>	<i>908.00</i>
29	REAR OUTER TAIL LIGHT TRIM - LH	1	\$ 34.00	<i>\$</i>	<i>26.40</i>
30	REAR INNER TAIL LIGHT TRIM - LH	1	\$ 34.00		
31	REAR OUTER TAIL LIGHT - RH	1	\$ 1,135.00		
32	REAR INNER TAIL LIGHT - RH	1	\$ 1,135.00	<i>\$</i>	<i>908.00</i>
33	REAR OUTER TAIL LIGHT TRIM - RH	1	\$ 34.00		
34	REAR INNER TAIL LIGHT TRIM - RH	1	\$ 34.00		
35	REAR WARNING TRIANGLE	1	\$ 213.00		
36	REAR WARNING TRIANGLE RETAINER	1	\$ 65.00		
37	REAR LID TRIM PANEL	1	\$ 365.00		
38	REAR CROSS PANEL	1	\$ 274.00	<i>\$</i>	<i>218.80</i>
39	REAR CROSS PANEL REINFORCEMENT	1	\$ 532.00	<i>\$</i>	<i>425.20</i>
40	REAR CROSS PANEL TRIM	1	\$ 185.00	<i>\$</i>	<i>148.00</i>
SUB TOTAL SPARE PARTS		:	\$ 6,853.00	<i>\$</i>	<i>11,121.60</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 1512 G

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	11,121.60
41	THREE-POINT AUTOMATIC SEAT BELT - LH / RH	2	\$ 2,454.00	\$	1,963.20
42	SEAT BELT HEIGHT ADJUSTER - LH / RH	2	\$ 384.00	\$	307.20
43	AIRBAG CONTROL UNIT	1	\$ 2,364.00	\$	1,891.20
44	CENTRAL PROTECTION	1	\$ 590.00	\$	472.00
45	REAR TAILGATE CHROME TRIM STRIP - CENTER	1	\$ 272.00	\$	217.60
46	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
47	STONE CHIP	S/N	\$ 180.00	\$	180.00
48	REAR NO PLATE	S/N	\$ 80.00		
49	SUPPLEMENTARY		\$ 890.00	\$	795.36
50	SUNDRIES		\$ 300.00	\$	64.96
TOTAL SPARE PARTS		:	\$ 25,936.00	\$	17,193.12
TOTAL LABOUR CHARGES		:	\$ 14,682.00	\$	10,332.00
GRAND TOTAL		:	\$ 40,618.00	\$	27,525.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-27/03/23



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1177/2022/EQ 18-Jan-23 CHANG 1 of 1 SNB 1512 G AUDI A4 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO CUT OUT AND WELD REINFORCEMENT FOR LH REAR SIDE PANEL.	\$ 1,000.00	\$ 500.00
2	TO RESPRAY SPARE WHEEL HOUSING.	\$ 1,100.00	\$ 550.00
		\$ 2,100.00	\$ 1,050.00
<u>Parts</u>			
1	REINFORCEMENT FOR SIDE PANEL - LH	\$ 243.00	\$ 194.40
2	TELEPHOPNE AERIAL	\$ 197.00	\$ 157.60
3	RETAINER FOR AERIAL	\$ 30.00	\$ 23.36
4	METAL FILLER POWDER	\$ 280.00	\$ 280.00
5	CAVITY WAX	\$ 140.00	\$ 140.00
	Parts	\$ 890.00	\$ 795.36
	Labour	\$ 2,100.00	\$ 1,050.00
GRAND TOTAL		\$ 2,990.00	\$ 1,845.36

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT