

Surveyor : RASUL
 Claim : TP ALLIED WORLD
 DOA : 21.12.2022
 Emailed : 17.03.2023, 8.10pm
 Date survey : 13.01.2023

VEHICLE NO : SMW 7108 C
 MODEL : CITROEN GRAND C4 SPACETOURER 1.2
 WIP : 19376

Material	:	\$	10,218.00
Labour	:	\$	6,440.00
Sub-Total	:	\$	16,658.00
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	16,658.00
GST 8%	:	\$	1,332.64
Grand Total	:	\$	17,990.64
Finalise By/Date	:	LOI /	17/03/2023

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 7 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 9

☒ TP claim YQ 7460 Z

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
SAYEERAJAN SARVESWARAN		Cust No/Name /SAYEERAJAN SARVESWARAN	
234 WESTWOOD AVENUE		Reg No/Reg Date SMW7108C / 04/12/2020	
#10-35		Date In/Mileage 20/02/2023/ 26263	
SINGAPORE 648361		Chassis/Package VF73AHNSRKJ816635 /#	
Contact No Mobile: 85714690		Engine No 10XVAC0065898	
		Make/Model CIT/GRAND C4 SPACETOURE 1.2 EURO 6.2	
		Colour/Trim MOP RUBY RED / 8LF STANDARD AMBIAN	



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CTP00073	Cash	17/03/2023/ 20:04	TLV	260 / AiTing	19376	0		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, FRONT BUMPER, REPAIR REAR TAILGATE, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2280.00
E PNT88000 REMOVE AND REINSTALL SENSOR TO FACILITATE REPAIR								✓ 60.00
E PNT98000 RESPRAY ON FRONT BUMPER, REAR BUMPER, REAR TAILGATE, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1650.00
A 10028901 CONDUCT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								✓ 380.00
A 10028901 CHECK WIRING AND ELECTRICAL COMPONENTS TO FACILITATE REPAIR								✓ 100.00
M SUNDRY ANTI RUST PROOFING ON AFFECTED AREAS TO THE SAME								✓ 100.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 80.00
E PNT88000 REMOVE & REINSTASLL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST → Supp.								380.00
M SUNDRY SUPPLY REAR WINDSCREEN GLASS SEALANT → Supp.								80.00
E PNT88000 REPLACE TAILGATE → Supp.								760.00
E PNT98000 RESPRAY TAILGATE → Supp.								550.00
X REAR BUMPER					1.00	✓ 1503.00	0.00	1503.00
X BUMPER BRACKET					1.00	✓ 709.00	0.00	709.00
X BRACKET SET LAT					1.00	✓ 210.00	0.00	210.00
X FRONT BUMPER					1.00	✓ 1589.00	0.00	1589.00
X GUARD GRILLE INFERIEUR					1.00	✓ 469.00	0.00	469.00
X BMPR RUBBR BOOT					1.00	✓ 303.00	0.00	303.00

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
SAYEERAJAN SARVESWARAN		Cust No/Name /SAYEERAJAN SARVESWARAN	
234 WESTWOOD AVENUE		Reg No/Reg Date SMW7108C / 04/12/2020	
#10-35		Date In/Mileage 20/02/2023/ 26263	
SINGAPORE 648361		Chassis/Package VF73AHNSRKJ816635 /#	
Contact No Mobile: 85714690		Engine No 10XVAC0065898	
		Make/Model CIT/GRAND C4 SPACETOURER 1.2 EURO 6.2	
		Colour/Trim MOP RUBY RED / 8LF STANDARD AMBIAN	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	17/03/2023/ 20:04	TLV	260 / AiTing	19376	0

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X BUMPER BRACKET		1.00	423.00	0.00	423.00
X HEADLIGHT ASSY LH		1.00	1063.00	0.00	1063.00
X BUMPER BRACKET		1.00	265.00	0.00	265.00
X BUMPER BRACKET		1.00	491.00	0.00	491.00
X TAILGATE		1.00	2988.00	0.00	2988.00
X BADGE		1.00	91.00	0.00	91.00
X BADGE		1.00	114.00	0.00	114.00
Z TEXT					
TP CLAIM ALLIED WORLD YQ7460Z					
DOA : 21.11.22					
SURVEYOR RASUL 13.01.23					
REPAIR 07 DAYS					

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	10,218.00	Nett	16,658.00
Labour	6,160.00	8% GST on	1332.64
Standard Menu	0.00		
Specialist Job	80.00		
Diagnostics Job	0.00	Total Payable	17,990.64
Sundry/Others	200.00	Paid	0.00
Total(w/o GST)	16,658.00	Total Due	17,990.64

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

INSURANCE CO. : ALLIED WORLD

Supplementary Parts For Registration No.: SMW 7108 C

<u>Parts</u>		<u>Cost (\$)</u>
1	Headlight assy LH	1,063.00
2	Bumper Bracket	265.00
3	Bumper bracket	491.00
4	Tailgate	2,988.00
5	Badge	91.00
6	Badge	114.00
Total Parts		5,012.00
<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & reinstall rear windscreen glass and conduct water leak test	380.00
2	Supply rear windscreen glass sealant	80.00
3	Replace tailgate	760.00
4	Respray tailgate	550.00
Total Labour		1,770.00
Taxable amount		6,782.00
8% GST		542.56
Grand total		<u>\$ 7,324.56</u>

Thank You.

Yours faithfully

LOI AI TING
Senior Officer - Admin
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240