

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG23000366/AVP3E2**Date:** 03/04/2023REFERENCE

|                   |              |                  |            |           |              |
|-------------------|--------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | CHEW SIN WAN | Policy No:       | 1900167318 |           |              |
| Date of Loss:     | 01/01/2023   | Nature of Claim: | OD         | Claim No: | 0523357444SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                         |  |             |                  |
|-----------------------------|-----------------------------------------|--|-------------|------------------|
| Reg No:                     | <b>SLF6888S</b>                         |  | Engine No:  | DAX057355        |
| Make & Model:               | AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) |  | Chassis No: | WAUZZZF1K2110123 |
| Reg. Date:                  | 27/09/2019 (Man. Year: 2019)            |  | Odometer:   | 64310 km         |
| Colour:                     | White                                   |  |             |                  |
| Engine Capacity:            | 1984 cc                                 |  |             |                  |
| Market Value/New Car Price: | S\$172,000.00                           |  |             |                  |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>       |  |             |                  |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 235/55 R19  | Rear Tyre Size:  | 235/55 R19  |
| Front Left Side:  | Falken 6 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 22,151.00         | 6,851.60          | 15,299.40         | 69.07         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 9,892.00          | 3,352.00          | 6,540.00          | 66.11         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>32,043.00</b>  | <b>10,203.60</b>  | <b>21,839.40</b>  | <b>68.16</b>  |
| <b>- Excess (S\$)</b>               | <b>2,000.00</b>   | <b>2,000.00</b>   | <b>0.00</b>       | <b>0.00</b>   |
| <b>(S\$)</b>                        | <b>30,043.00</b>  | <b>8,203.60</b>   | <b>21,839.40</b>  | <b>72.69</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b>       | <b>2,403.44</b>   | <b>656.29</b>     | <b>1,747.15</b>   | <b>72.69</b>  |
| <b>Nett Amount (S\$)</b>            | <b>32,446.44</b>  | <b>8,859.89</b>   | <b>23,586.55</b>  | <b>72.69</b>  |

INSPECTION

|                             |            |               |                                                                        |
|-----------------------------|------------|---------------|------------------------------------------------------------------------|
| Date of Assignment:         | 12/01/2023 |               |                                                                        |
| Date Inspected:             | 10/01/2023 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                        |

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|---------------|-------------|--------------|
| 1   | 2   |          | *REAR BUMPER - UPPER / LOWER             | Deformed      | 3,360.00 FS | *2,688.00 FS |
| 2   | 1   |          | *REAR BUMPER SPOILER                     | Deformed      | 966.00 FS   | *772.40 FS   |
| 3   | 1   |          | *REAR BUMPER TOW EYE COVER - LH          | Not Necessary | 54.00 FS    | *- FS        |
| 4   | 1   |          | *REAR BUMPER CLOSING ELEMENT - LH        | Not Necessary | 108.00 FS   | *- FS        |
| 5   | 1   |          | *REAR BUMPER CHROME TRIM - LH            | Not Necessary | 265.00 FS   | *- FS        |
| 6   | 1   |          | *REAR BUMPER LIGHT - LH                  | Cracked       | 779.00 FS   | *622.80 FS   |
| 7   | 1   |          | *REAR LID LIGHT - LH                     | Cracked       | 1,859.00 FS | *1,487.20 FS |
| 8   | 1   |          | *REAR BOOT LID OPENING CONTROL UNIT      | Not Necessary | 484.00 FS   | *- FS        |
| 9   | 1   |          | *REAR TAILGATE OPENING SENSOR LINE       | Not Necessary | 128.00 FS   | *- FS        |
| 10  | 1   |          | *REAR AERIAL KEY ACCESS                  | Not Necessary | 120.00 FS   | *- FS        |
| 11  | 1   |          | *REAR BUMPER REINFORCEMENT BEAM          | Not Necessary | 1,043.00 FS | *- FS        |
| 12  | 2   |          | *REAR BUMPER IMPACT BAR GASKET - LH / RH | Not Necessary | 7.00 FS     | *- FS        |
| 13  | 1   |          | *REAR BUMPER HOLDING STRAP               | Not Necessary | 189.00 FS   | *- FS        |
| 14  | 1   |          | *REAR BUMPER GUIDE SECTION - LH          | Not Necessary | 95.00 FS    | *- FS        |
| 15  | 2   |          | *REAR PARKING AID SENSOR - INNER / OUTER | Not Necessary | 531.00 FS   | *- FS        |
| 16  | 4   |          | *REAR PARKING AID SEAL RING              | Not Necessary | 10.00 FS    | *- FS        |
| 17  | 1   |          | *SET REAR BUMPER WIRING                  | Not Necessary | 544.00 FS   | *- FS        |
| 18  | 1   |          | *REAR LID                                | Repair        | 4,975.00 FS | *- FS        |
| 19  | 1   |          | *REAR LID ATTACHMENT PARTS               | Not Necessary | 170.00 FS   | *- FS        |
| 20  | 1   |          | *REAR LID FLAP GASKET                    | Not Necessary | 431.00 FS   | *- FS        |
| 21  | 1   |          | *BONNET LOCK COVER                       | Not Necessary | 8.00 FS     | *- FS        |
| 22  | 1   |          | *PACKING ADHESIVE                        | Necessary     | 21.00 FS    | *16.80 FS    |
| 23  | 1   |          | *AUDI EMBLEM                             | Necessary     | 144.00 FS   | *114.80 FS   |
| 24  | 1   |          | *Q5 INSCRIPTION                          | Necessary     | 104.00 FS   | *82.80 FS    |
| 25  | 1   |          | *QUATTRO INSCRIPTION                     | Necessary     | 104.00 FS   | *82.80 FS    |
| 26  | 1   |          | *REAR WINDOW                             | Not Necessary | 1,274.00 FS | *- FS        |
| 27  | 1   |          | *WINDOW PRIMER                           | Not Necessary | 22.00 FS    | *- FS        |
| 28  | 2   |          | *REAR SPOILER - LH / RH                  | Not Necessary | 520.00 FS   | *- FS        |
| 29  | 1   |          | *REAR SPOILER FIXING PARTS               | Not Necessary | 36.00 FS    | *- FS        |
| 30  | 1   |          | *REAR SPOILER FOAM STRIPS                | Not Necessary | 36.00 FS    | *- FS        |
| 31  | 2   |          | *REAR WHEEL COVER - LH / RH              | Necessary     | 1,230.00 FS | *984.00 FS   |
| 32  | 1   |          | *REAR SILENCER                           | Not Necessary | 1,551.00 FS | *- FS        |
| 33  | 2   |          | *REAR SILENCER BRACKET - LH / RH         | Not Necessary | 124.00 FS   | *- FS        |
| 34  | 1   |          | *REAR SILENCER HEAT SHIELD               | Not Necessary | 159.00 FS   | *- FS        |
| 35  | 1   |          | *REAR WINDSCREEN SEALANT                 | Not Necessary | 200.00 FS   | *- FS        |
| 36  | 1   |          | *SUNDRIES                                | Not Necessary | 500.00 FS   | *- FS        |

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **22,151.00**      **6,851.60**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                         | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                     |          |                 |                 |
| 1                              | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR                                                                                    | New      | 360.00          | 360.00          |
| 2                              | TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY                                      | New      | 480.00          | 0.00            |
| 3                              | TO RENEW REAR WINDSCREEN                                                                                                                            | New      | 480.00          | 0.00            |
| 4                              | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN                                                                                                           | New      | 400.00          | 0.00            |
| 5                              | TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN                                                                                                 | New      | 200.00          | 0.00            |
| 6                              | TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS                                              | New      | 4,500.00        | 2,050.00        |
| 7                              | TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION                                                                                            | New      | 480.00          | 0.00            |
| 8                              | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                       | New      | 192.00          | 192.00          |
| 9                              | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 2,800.00        | 750.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                     |          | <b>9,892.00</b> | <b>3,352.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >