

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0009/2023/EQ
DATE : 6-Jan-23
WIP : 57430

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/01/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHEW SIN WAN
ADDRESS : 6 PRIMROSE AVENUE
TELEPHONE : HP +65 92707582
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SLF 6888 S**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 27/9/2019
ENGINE NO : DAX 057355
CHASSIS NO : WAUZZZFY1K2110123
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Jan-23
PLACE OF ACCIDENT : 91 UPPER CHANGI ROAD FAR SUMMER GARDENS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 6888 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN.	S/N \$	480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	✓
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	500 750
TOTAL LABOUR CHARGES		:	\$ 4,720.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 6888 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$	4,500.00	2050 2050
8	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$	480.00	+
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 9,892.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER / LOWER <i>zchnd</i>	2	\$ 3,360.00	✓ 2688
2	REAR BUMPER SPOILER <i>zchnd</i>	1	\$ 966.00	✓ 772.40
3	REAR BUMPER TOW EYE COVER - LH <i>neu</i>	1	\$ 54.00	✓
4	REAR BUMPER CLOSING ELEMENT - LH <i>neu</i>	1	\$ 108.00	+
5	REAR BUMPER CHROME TRIM - LH <i>Not Nec</i>	1	\$ 265.00	+
6	REAR BUMPER LIGHT - LH <i>amld</i>	1	\$ 779.00	✓ 622.80
7	REAR LID LIGHT - LH <i>amld</i>	1	\$ 1,859.00	✓ 1487.20
8	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 484.00	+
9	REAR TAILGATE OPENING SENSOR LINE	1	\$ 128.00	+
10	REAR AERIAL KEY ACCESS	1	\$ 120.00	+
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,043.00	+
12	REAR BUMPER IMPACT BAR GASKET- LH / RH <i>neu</i>	2	\$ 7.00	+
13	REAR BUMPER HOLDING STRAP <i>neu</i>	1	\$ 189.00	+
14	REAR BUMPER GUIDE SECTION - LH	1	\$ 95.00	+
15	REAR PARKING AID SENSOR- INNER / OUTER <i>neu</i>	2	\$ 531.00	+
16	REAR PARKING AID SEAL RING <i>neu</i>	4	\$ 10.00	+
17	REAR BUMPER WIRING SET <i>neu</i>	1	\$ 544.00	+
18	REAR LID <i>Repair</i>	1	\$ 4,975.00	+
19	REAR LID ATTACHMENT PARTS <i>neu</i>	1	\$ 170.00	+
20	REAR LID FLAP GASKET <i>neu</i>	1	\$ 431.00	+
SUB TOTAL SPARE PARTS			\$ 16,118.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	BONNET LOCK COVER <i>Not in</i>	1	\$ 8.00	+	
22	PACKING ADHESIVE <i>2</i>	1	\$ 21.00	✓	16.80
23	AUDI EMBLEM <i>Na</i>	1	\$ 144.00	✓	114.80
24	"QS" INSCRIPTION <i>Na</i>	1	\$ 104.00	✓	82.80
25	"QUATTRO" INSCRIPTION <i>Na</i>	1	\$ 104.00	✓	82.80
26	REAR WINDOW <i>Not in</i>	1	\$ 1,274.00	+	
27	WINDOW PRIMER <i>Not in</i>	1	\$ 22.00	+	
28	REAR SPOILER - LH / RH <i>Not in</i>	2	\$ 520.00	X	
29	REAR SPOILER FIXING PARTS <i>Not in</i>	1	\$ 36.00	+	
30	REAR SPOILER FOAM STRIPS <i>Not in</i>	1	\$ 36.00	+	
31	REAR WHEEL COVER - LH / RH <i>Na</i>	2	\$ 1,230.00	✓	984
32	REAR SILENCER <i>Not in</i>	1	\$ 1,551.00	+	
33	REAR SILENCER BRACKET - LH / RH <i>2</i>	2	\$ 124.00	+	
34	REAR SILENCER HEAT SHIELD <i>Not in</i>	1	\$ 159.00	+	
35	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	+	
36	SUNDRIES <i>nn</i>		\$ 500.00	?	X
TOTAL SPARE PARTS		:	\$ 22,151.00		
TOTAL LABOUR CHARGES		:	\$ 9,892.00		
GRAND TOTAL		:	\$ 32,043.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *10/01/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT